

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T 45N R 30W	A9 (GCDB 100300)
	T 45N R 30W	A8 (GCDB 100340)
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 04/19/16 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A9) Corner common to Sections 24-25 T45N-R31W and Sections 19-30 T45N-R30W. 1969 - Restablished by  
A.O.Enger RLS from local evidence and 1933 Marquette County Road Commission notes. Set 1"IDx36"  
I.pipe with 4" aluminum cap. B.Spruce 7" S27°E 68.5 links, B.Spruce 7" S23°W 99 links.

(A8) Quarter corner common to Sections 24 T45N-R31W and 19 T45N-R30W. 1969 - Reestablished by  
A.O.Enger RLS 40.00 chains north of A9 and on line between A9 and A7. Set 1"IDx36" I.pipe with 4"  
aluminum cap. B.Spruce 4" S5 1/2°W 8.5 links, B.Spruce 5" N57°W 31 links, Balm of Gilead 12" N41°E  
14.5 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A9) Found the 1969 monument in good condition, the 1969 witnesses no longer evident. Verified the  
position of the corner with respect to 1/4 corner A8 2642.13' north (AOE record 40.00 chains) and  
being 1.9' west of straight line through A7-A8 (AOE record on line). I note that this position was  
used by an unknown surveyor to control the reestablishment of 1/4 corner L9 T45N-R31W at least 15  
years ago. I accept the monument as a careful and faithful reestablishment of the position of the  
original corner.

(A8) Found the 1969 monument in good condition, in accord with the 1969 record position, and at  
record bearing and distance from the 1969 witnesses, now all rotted stumps. Accepted the monument  
as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A9) Found 1"ID I.pipe with MI Dept. of Conservation  
cap. Set measuring nail with MDNR tag in the side  
of:  
7" Balsam N60°E 15.2' mrkd "S19 NBT"  
8" Balsam S44°E 54.95' "S30 NBT"  
21" W.Birch S58°W 73.7' "S25 NBT"  
Power pole 4531 24R25 N79°W 41.85'  
Set sq'd cedar post adjacent.  
E= 7913882.625 N= 166460.293

(A8) Found 1"ID I.pipe with 4" alum. MI Dept. of  
Conservation cap. Set measuring nail with MDNR  
tag in the side of:  
5" Balsam N29°W 11.1' mrkd "1/4S NBT"  
5" Balsam N24°E 9.95' do  
3" Balsam S83°E 5.75' do  
5" Balsam S36°W 10.75' do  
Set sq'd cedar post adjacent.  
E= 7913892.391 N= 167265.421

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum  
Coord. Ref.=NGS PID RL0202: N= 156159.364 m. E= 7917031.370 m.

Signed by Stephan J. Szyszkoski Date 04/25/2016  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

