SURVEY & REMONUMENTATION

MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECOPD

ADD 9 8 1095

1994 DEC 29 PM 1: 55

		ALKRO		HER RECORDATION CEN		OLO 20) IN 1: 25				
	r corners in		ISSION Filing Requi	rement of Act 74, Mich.	P.A. 1970	Patricia A	Markey				
	Marquette		Located In:	Corner Code ##	·	REGISTER C	FOTTOS (
1.	Public Land	•	46N 25W T R T R	K-8	PATIFIED BY PEEF	R GROUP	Y				
			T R		DATE Sint 26						
2.	Property Co	introlling	T R S T R		,	/ /	_				
_	in Section		S T R			LIBER	L PAGE 22"				
3.	Miscellaneo Property in		S T R S T R		Register of Dec	eds Stamp & File	Number				
						<u></u>					
			corded Plat		A B C	DEFGH	I J K L M				
<i>,</i> .	THAIC CIAI				2 6	- 53					
				Ctb 0.4	3	1 1 1 1					
	Michael M		in a field survey on	September 94		8 9 10	11-1-12-				
n li curi Mar Moo Cou	hereby certify to ines 1 and 2 a rent manual of nagement or by ove were in con	that under requisitions were in construction of survey instructions and decree of a Conformance with stablished, re-	irements of P.A. 74, Michigan P.A. conformance with regulations a stions of the United States Department of Law and/or that the corrected rules of the Michigan Board established, monumented, re	A. of 1970, the corner points mer and rules therefore as required artment of the Interior, Bureau of her points mentioned in lines 3, I of Land Surveyors or by a Deci	ntioned 6 18 19 19 19 19 19 19 19 19 19 19 19 19 19	-171615 -202122 -292827	23 24 25				
10		re than 4 cor certificate.	rners, all in the same town a	and range, may be recorded	d 11 12 31	32 33 34	35 36				
	Description	of original ma	onument and accessories a	nd/or subacquant soctoratio	13						
	·		ter Corner Section 23;	•	и.		•				
	in 1 Fir and	845 and n 6 S73°E 1 I a	ablished during U.S. Sunonumented with a wo 2 lks. 8 N33°W 15lks.			Oouglass Hou	ghton, D.S.				
	Description	of corner evid	dence found and/or method	applied in restoring or rees	stablishing corner:						
	K-8; Eas	t One-quar	ter Corner Section 23;	,		÷					
	fee	Found ½" iron rod in concrete. Found no evidence of U.S. bearing trees. Found monument is 11.4 feet south and 3.9 feet west of being midway and on line between appropriate controlling section corners.									
				Grid Syste	ne Coordinates: em - NAD 83 ber - 2111 Michiga - International = 578493.41 = 26149141.	Feet 172					
	Description (of monument	for corner and accessories	established to perpetuate I	ocating the position of	the corner:					
	K-8; Eas	t One-quar	ter Corner Section 23;		TE	F MICHIO					
	See	back of fo	orm.		PROFI SUF	HAEL D. LESKI ESSIONAL RVEYOR No. 19091	**************************************				
	•		\ \ \ .		A OF	ESSION PARTIE					
		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	. \ \\		`						

CATALOR JEN

A.C Description of monument for corner and accessories established to perpetuate locating the postion of the corner:

K-8; East One-quarter Corner Section 23;

Replaced found $\frac{1}{2}$ " iron rod in concrete with 2" I.D. x 30" aluminum pipe with 3" aluminum cap (Berntsen A1NB30) appropriately stamped as to location.

Set 60d spike	E/side	11" Red Oak	N16°E	248.16'
Set 60d spike	N/side	6" Red Oak	N54°E	121.69'
Set 60d spike	N/side	9" Red Oak	S89°E	91.40'
Set 60d spike	W/side	8" Red Oak	SO9°E	347.31'
		Location Post	North	1.5'

All of the above new bearing trees marked with upper and lower face blazes and scribed "NBT".