

43

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Marquette

Located In:

Corner Code //

1. Public Land Survey T 46N R 28W L7
T 46N R 28W L9
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

L9 January 24, 1995

I, Paul R. Bressette, in a field survey on L7 January 25, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- (L7) Quarter corner common to Sections 13 and 24. 1983: Keith Sackett, RLS 19006. Set DNR monument witnessed by: 10" J. Pine N41E 9.6'; 9" J. Pine S28E 15.1'; 9" J. Pine N89W 24.3'. Recorded in Liber 5 RC, P.8, Marquette County Records.
(L9) Quarter corner common to Sections 24 and 25. 1983: Dave Erickson, RLS 29245. Set 5/8" rebar with plastic cap witnessed by: 12" J. Pine N04E 17.52'; 6" J. Pine S88E 7.87'; 10" J. Pine S03W 35.68'; 6" J. Pine S82W 23.49'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- (L7) Found monument and witnesses as described. Due to an error found in Sackett's calculations, monument was 135.14 feet south of intended position. A new monument was set in the correct position, mid-point and on-line between the Northeast and Northwest corners of Section 24. The old witnesses were defaced, the cap was broken off the old monument and the pipe was driven below grade.
(L9) Found 5/8" rebar with plastic cap and one witness (J. Pine East 7.90' measured) as described. Accepted monument as found and re-witnessed.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- (L7) DNR monument
4" J. Pine N23E 3.9'
8" J. Pine S23E 36.0'
5" J. Pine S16W 30.3'
8" J. Pine N46N 25.7'
All trees were face and butt blazed, scribed 1/4S, NBT. Measurements are to notch in butt blaze. Bearings are magnetic.
(L9) 5/8" rebar w/ plastic cap
6" J. Pine N27E 27.65'
8" J. Pine East 7.6' (7.90' to nail) 5" J. Pine S39W 52.05'
3" J. Pine N34W 24.1'
All trees are face and butt blazed, scribed 1/4S, NBT. Measurements are to notch in butt blaze. Bearings are magnetic.



Signed by Paul R. Bressette Date
Surveyor's Michigan License No. 37270

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

For the Michigan Department of Natural Resources - Forest Management Division