

Part A continued:

84 437

1977: Certificate of Survey recorded in L. 1 page 177, recorded by Joseph O. Wasie, L.S. #15415 indicates the West quarter corner of Section 9 as a found square bolt.

1978: Sketch of County Roads in the area recorded in L. 100 page 91 indicates the East quarter corner Section 8.

1978: The West quarter corner of Section 9 shown on the recorded plat of Sunccliffe No. 1 recorded by Robert F. Cambensy, L.S. #19616 indicates the corner to be 78.02' South of the centerline of M-28 Business Route.

1978: Land Corner Recordation Certificate recorded in L. 1 RC, Page 323 by Charles F. Clark, L.S. #25836 indicates an Iron Bolt witnessed by:
P.K. Nail in Power Pole S44E, 35.80'
Northeast corner of Building S40W, 48.60'
Stop Sign Post N49E, 35.45'

1982: Survey Sketch prepared by Engineering Consultants recorded in L. 109, page 317 indicates the East quarter corner Section 8 distance of 1328.9 to the sixteenth corner West.

1985: Land Corner Recordation Certificate recorded in L. 5 RC, Page 53 by James Minard, L.S. #30091 indicates a set 6" spike in street due to previous corner being destroyed by construction work. Spike is witnessed by:

Northwest corner Gas Station S60W, 80.40'
Southeast corner Gas Station S25W, 75.30'
P.K. Nail in utility pole S45E, 35.77'
Most Easterly Anchor Bolt on concrete Gas Pump Island S45W, 38.54'

1992: A Certificate of Survey recorded in L. 387, Page 689 by Larry J. Bussone, L.S. #25833 indicates the West quarter corner of Section 9. Distance East 1318.96' to the sixteenth corner.

1992: A Certificate of Survey recorded in L. 002, Page 34 by Larry J. Bussone, L.S. #25833, indicates the West quarter corner of Section 9 as a found iron.

1993: A Certificate of Survey recorded in L. 002 Page 62 by Larry J. Bussone, L.S. #25833, indicates the West one quarter corner of Section 9 as a found Iron Pin in road.

1999: A Certificate of Survey recorded in L. 2, Page 439 by Larry J. Bussone, L.S. #25833, indicates the East quarter corner of Section 8 as an iron. The distance West 1328.76' to the sixteenth corner.

2000: A certificate of Survey by Robert R. Spear Jr., P.S. #43069, indicates a found PK Nail in the centerline of Cooper Lake Road witnessed by:

NE corner of building S37W, 48.60'
NW corner of building S62W, 80.40'
Power pole S44E, 35.41'
found 1" Iron N69-37-29E, 3.70' (note: this was later discovered as a magnetic rock in a hole in the asphalt)

**SURVEY &
MONUMENTATION**

FEB 21 2001

SECTION