## SURVEY & REMONUMENTATION

MARQUETTE COUNTY MICHIGAN RECEIVED FOR RECORD

JOB NUMBER: 94030

APR 2 8 1995

LAND CORNER RECORDATION CERTIFICATE I, Mich. P.A. 1970

1994 DEC 28 PM 5: 56

SHEET NO. : 1-472	COMMISSION Filing Requirement of Act 7	4
For corners in	COMMISSION	

	MARQUETTE (County)	Located In:	Corner Code <del>:</del> ≠≠	Policia d. Manley &
1.	Public Land Survey	T <sub>47N</sub> R <sub>24N</sub> T R T R T R T R	-H-5	
2.	Property Controlling in Section	S T R S T R		LIBER 1 PAGE 143
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
		, Recorded Plat		A B C D E F G H 1 J K L

in a field survey on I, \_\_\_\_\_\_\_, in a field survey on \_\_\_\_\_\_, note that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	A	8	Ç	D	E	F	G	H	<u>1</u> J	K	L	_ N
2		[ 6—-		[ 5—		4 -	L	3		Ĭ		
3	L	1_	ļ_		L	<u> </u>	┡	1_	<u> </u>			L.
4	上	ļ 7	↓_	 8—	L	ا و	丄	 10	<u>_</u> ,	ļ,	L	2
5	_	<u> </u>	<u> </u>	Ĺ	L	ļ_	L	_				<u> </u>
6		 18	<u>L</u> .	  7—	L	 16—	上	[ 15	1	ļ	1	] 3—
7	<u> </u>	_	<u> </u>	<u> </u>		_	上	<u> </u>	_	<u> </u>		<u> </u>
8	_	 19—	L_2	 20	L,	 21	$\perp$	22	2	3—	 	4
9			L			L	L	Ī_	ļ			<u> </u>
10	<u> </u> _:	30—	<u>L</u> ,	 	Ļ,	28-		 27—	2	6—	<u></u> ;	5_
11	L	1		<u> </u>		_	$oxed{oxed}$		_	$\sqcup$		_
12	L:	 31—	Ļ,	 32—	Ļ	 3 <b>3-</b>	$oxed{\bot}$	 34	<u> </u> _3	5		  6
13						ŧ	1	Ī				1

A. Description of original monument and accessories and/or subsequent restoration:

H-5: North 1/4 Corner of Section 15, T47N-R24W. 1845: A.D. Sullivan's original subdivision survey notes describe the corner monument as wood post referenced by: (No size given) Black Ash S60W, 31 L

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1994: No original evidence found. Corner position calculated proportional distnace on line between the NW Corner of the NE Corner of Section 15. Distance West is 2640.05' and distance East is 2639.39'. The GLO chainage was 79,73 for the mile and 39.86 for the East 1/2 mile. The Corner falls in an extremely swampy area where GLO river calls were inconclusive.

> THE STEEL BY PEER GROUP 1 345 OF 1990 Bussing

	DATE Nov 7, 1994
C.	Description of monument for corner and accessories established to perpetuate locating the position of the corner:
	1994 - Set a 2 1/2" diameter aluminum pipe capped with a 3 1/4" diameter aluminum tablet Narquette County Survey  Monument stamped to identify the corner referenced by:  11" Black Ash S25W 25.06 ft. (measured to nail)  Steel sign post N04E 17.24 ft. (with BT tag)  Steel sign post N38E 22.55 ft. (with BT tag)  Steel sign post S53B 24.04 ft. (with BT tag)  Steel sign post S39W 24.04 ft. (with BT tag)  Steel sign post Due South 1.05 ft. (with Survey Marker sign)  Monument is in wet area and is 0.5' above ground. Measured to face of sign posts. Bk. 7, Pg. 117  GERALD W.
	The state of the s