

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T 48N R 30W	G5
	T R	(GCDB 400500)
	T 48N R 30W	G7
	T R	(GCDB 400400)
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Stephan J. Szyszkoski, in a field survey on 07/09/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G5) Section corner common to 9-10-15-16. 1848 - Established by Wells Burt, Deputy Surveyor. Set
post. Spruce 10" S25°E 21 links, Spruce 10" N14°W 9 links. Found no subsequent record.

(G7) Section corner common to 15-16-21-22. 1848 - Established by Wells Burt, Deputy Surveyor.
Cedar 24" for corner. Spruce 12" N45°E 10 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G5) The original post and accessories were not recovered. Found no evidence of the position of the
original corner on the ground. Reestablished the position for the corner by double proportionate
measurement to the original record between corners 15811.02' east (240.15 ch R); 7895.94' south
(120.00 ch R); 2632.52' north (40.00 ch R); and 7930.28' west (120.45 ch R).

(G7) The original corner tree and accessory were not recovered. Found no evidence of the position
of the original corner on the ground. Reestablished the position for the corner by double
proportionate measurement to the original record between corners 2632.05' south (40.00 ch R);
10536.05' east (160.26 ch R); 7896.05' north (120.00 ch R); and 5259.64' west (80.00 ch R).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" B.Spruce N88°E 25.0' mrkd "S10 NBT"
8" B.Spruce S45°E 6.7' "S15 NBT"
12" W.Spruce S46°W 43.6' "S16 NBT"
4" Maple N14°W 28.5' "S9 NBT"
Set sq'd cedar post adjacent.
E= 7919170.279 N= 198465.843

(G7) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Maple N57°E 8.4' mrkd "S15 NBT"
7" Maple S76°E 15.4' "S22 NBT"
4" Sugar S19°E 10.5' "S21 NBT"
6" Sugar S15°W 21.25'
Set sq'd cedar post adjacent.
E= 7919147.333 N= 196861.830

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID AA8080: N= 198400.952 m. E= 7925456.741 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/12/2014

For the Michigan Department of Natural Resources, Forest Resources Division

