

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T 48N R 30W	E4
	T R	(GCDB 300540)
2. Property Controlling in Section	T 48N R 30W	E5
	T R	(GCDB 300500)
3. Miscellaneous Property in Sec.	S T R	
	S T R	
	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 07/08/14 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-  
established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E4) Quarter corner common to Sections 8&9. 1848 - Established by Wells Burt, Deputy Surveyor  
midway and on the Section line between Section corners 40.00 chains north and south. Set Cedar  
post. Sugar 10" S70°E 35 links, Cedar 14" N69°W 25 links. Found no subsequent record.

(E5) Section corner common to Sections 8-9-16-17. 1848 - Established by Wells Burt, Deputy  
Surveyor. Set Fir post. Spruce 9" S40°E 34 links, Y.Birch 24" N7°7W 15 links. Found no subsequent  
record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E4) The original post and accessories were not recovered. Found no evidence of the position of the  
original corner on the ground. Reestablished the position for the corner midway and on the Section  
line between Section corners 2621.55' north and south. The position for the corner falls on a rock  
knob 20' high. The monument was driven to refusal (about 0.75' deep) and was made firm in a rock  
mound.

(E5) The original post and accessories were not recovered. Found no evidence of the position of the  
original corner on the ground. Reestablished the position for the corner by double proportionate  
measurement to the original record between corners 5243.22' south (80.00 ch R); 2637.19' west (40.05  
ch R); 21104.55' east (320.55 ch R); and 7864.70' north (120.00 ch R).

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E4) Set 1"IDx28" I.pipe with 2" alum. MDNR cap made  
firm in a mound of rock 2 ft. dia.x 1 ft high. Set  
measuring nail with MDNR tag in the side of:  
8" Sugar N54°E 6.76' mrkd "1/4S NBT"  
3" W.Pine S80°E 5.34' do  
6" Maple S25°W 6.67' do  
4" W.Pine N69°W 6.35' do  
Set sq'd cedar post adjacent.  
E= 7917568.089 N= 199261.776

(E5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
5" Spruce S42°E 11.7' "mrkd "S16 NBT"  
9" Spruce S22°W 22.0' "S17 NBT"  
10" Spruce S63°W 19.7' "S17 NBT"  
11" Spruce N51°W 16.65' "S8 NBT"  
Set sq'd cedar post adjacent.  
E= 7917556.944 N= 198462.942

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)  
Coord. Ref.=NGS PID AA8080: N= 198400.952 m. E= 7925456.741 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 11/12/2014

For the Michigan Department of Natural Resources, Forest Resources Division

