## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	_ Located In:	Corner Code #	
Proporty Controlling	T 48N R 30W	(GCDB 700500)	
2. Property Controlling in Section	S T R S T R	(GCDB 240500)	86
3. Miscellaneous Property in Sec.	S T R		
4. Lot No. , Red 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number
instructions of the United States I a Court of Law and /or that the of the rules of the Michigan Board re-established, monumented, recover	74, Michigan P.A. of 1970, the corregulations and rules therefore as re Department of the Interior, Bureau corner points mentioned in lines 3, 4 d of Land Surveyors or by a Dec	11/21/13 do hereby state  The points mentioned in lines 1 and 2 equired in the current manual of survey of Land Management or by a decree of 1 and 5 above were in conformance with cree of a Court of Law; established, ange, may be recorded	, 5 , 6 — 18 — 17 — 16 — 15 — 14 — 13 —
	onument and accessories and		13

(M5) Corner common to Sections 12&13 T48N-R30W and Sections 7&18 T48N-R29W. 1846 - Established by John Burt, Deputy Surveyor, on the Range line between Section corner 80.00 ch. north and Quarter corner 40.00 ch. south. Set Spruce post. Spruce 10" S44°E 29 links, Spruce 9" N41°W 11 links. 1945 - County Road Commission notes in Field Book #656 imply that this corner existed at that time, as a measurement from here to the SE corner of Sec. 13 is given as 5255.2 feet. Found no description of the corner in the Rd. Commission field books.

(D5) Quarter corner common to Sections 8 and 17. 1848 - Established by Wells Burt, Deputy, on the section line between corners 40.05 chains east and west. Set Maple post. Y.Birch 20" S59°E 18 links, Spruce 8" N86°W 33 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M5) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner by single proportionate measurement to the original record between Section corner 5200.67' north (R=5280') and 1/4 corner 2600.33' south (R=2640'). From the position thus established an 8' high ridge, running E&W is 33' south (GLO record = 33 feet). The SE corner of Sec. 13 was not recovered. A comparison of distance with the 1945 record to that corner was thus not possible.

(D5) The original post was not recovered. Remonumented the corner at record bearing and distance from the original B.T. Y.Birch, now a 15' high partial stub, no scribing visible, interior rotted, overgrown upper blaze found previously cut open with chain saw and the blocks created thereby laying on the ground, adjacent. Suspect that the tree had been opened by Mead Corp. foresters circa 1995, as a dated MEAD poster is nearby. Their wood post, now down, was also found at record bearing and distance from the Y.Birch. Corner C5 is 2612.52' west and corner E5 2637.19' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M5) Set 1"IDX28" I.pipe with 2" alum. MDNR cap.  Set measuring nail with MDNR tag in the side of:  7" Cedar N64°E 21.45' mrkd "S7 NBT"  4" Cedar S29°E 16.55' "S18 NBT"  6" twin Sugar N79°W 18.2' "S12 NBT"  7" Cedar N22°W 16.95' "S12 NBT"  Sq'd a 3" balsam N37W 1.4' (no nail)  E= 7923988.234 N= 198400.952	(D5) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 12" Sugar N79°E 18.3' mrkd "1/4S NBT" 4" Sugar S29°E 7.2' do 7" Sugar S43°W 9.9' do 10" Sugar N07°W 5.6' w/MEAD poster do E= 7916753.627 N= 198487.095

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Coord. Ref.=NGS PID AA8080: N= 198400.952 m. E= 7925456.741 m.	
Signed by Stephen Szepholi. Date 11/12/2014	* STEPHAN J. * SZYSZKOSKI * LAND
Surveyor's Michigan License No. 33986	SURVEYOR
For the Michigan Department of Natural Resources, Forest Resources Division	No. 33986