

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette	Located In:	Corner Code #
(County)		
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 4 T 48N R 30W	12
	S _____ T _____ R _____	(GCDB 340620)
3. Miscellaneous Property in Sec.	S 16 T 48N R 30W	1
	S _____ T _____ R _____	(GCDB 320500)
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3						●							
4		7		8		9		10		11		12	
5						●							
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 12 09/03/14
1 08/28/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 4) Center-South 1/16 corner Sec. 4. Not established in the original survey.

(1-Sec. 16) West 1/16 corner between Sections 9 & 16. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 4) Corner not previously monumented. Established the position for the corner midway and on a straight line between Quarter corner 1289.12' south and Center of Section 4 1289.12' north.

(1-Sec. 16) Corner not previously monumented. Established the position for the corner midway and on the Section line between Section corner 1323.49' west and Quarter corner 1323.49' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 5" Maple S16°W 20.6' mrkd "1/16S BT" 6" twin Sugar S40°W 24.9' do 12" Sugar N40°W 33.8' do 10" Spruce N06°W 30.0' do Set sq'd Spruce post adjacent. E= 7918387.192 N= 200465.166	(1) Chiseled a "+" on bedrock at the corner position. Set measuring nail with MDNR tag in the side of (Wits are to "+"): 10" Maple N40°E 25.1' mrkd "1/16S BT" 10" Balsam S04°E 10.05' do 4" Maple S26°W 16.7' do 8" Cherry S75°W 7.4' do Set a 1"IDx28" I.pipe with 2" alum. cap 1.80' West of the corner position and on the Section line. Set sq'd Cedar post adjacent. E= 7917960.274 N= 198463.628
---	--

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
 Coord. Ref.=NGS PID AA8080: N= 198400.952 m. E= 7925456.741 m.

Signed by Stephan J. Szyszkoski Date 11/12/2014
 Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

