

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T 48N R 30W	G1 (GCDB 400700)
	T 49N R 30W	G13 (GCDB 400100)
2. Property Controlling in Section	S T R	(Same Corner)
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 07/16/14 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G1) Corner common to Sections 3 & 4 T48N-R30W and Sections 33 & 34 T49N-R30W. 1846 - Established
by John Burt, Deputy Surveyor. The 1846 notes for the line running west through this corner state
"79.50 Intersect stream 60 S.W. sluggish; 80.00 Corner of Sections 33 & 34 in stream; 1.43 Over
river". Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G1) Found no acceptable evidence of the position of the original corner. Reestablished the corner
position on the Township line and midway between Section corner I1 and E1 5268.24' east and west.
The position for the corner falls in the W.Branch of the Peshekee River and can not be monumented.
Established a WITNESS CORNER to the Section corner 30.00' west of the corner position and on the
Township line. The right bank of the river is 8' east of the WC position and is 11' south of the WC
position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G1) Set 1"IDx28" I.pipe with 2" alum. MDNR cap on
the Township line 30.00' west of the corner
position, for a WITNESS CORNER. Set measuring nail
with MDNR tag in the side of:
6" Balsam N15°E 3.3' mrkd "WC BT"
5" Balsam N39°E 12.7' do
8" Cherry S70°W 20.7' do
12" Spruce N55°W 22.1' do
Set cedar post adjacent.
E= 7919214.839 N= 201634.799 (the Witness Corner)



Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID AA8080: N= 198400.952 m. E= 7925456.741 m.

Signed by Stephan J. Szyszkoski Date 11/12/2014
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division