## REMONUMENTATION

MAY 2 2 1997

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	Filing Requirement of Act 74, Mich. P.A.	1970
MARQUETTE (County)	Located In: Corner Code #	RECORDED Dec. 26, 1996 AT 4: 20 O'CLOCK L.M
1. Public Land Survey	T 48NR 30W	REGISTER OF DEEDS
<ul><li>2. Property Controlling in Section</li><li>3. Miscellaneous Property in Sec.</li></ul>	S TR S TR S TR S TR	UBER 1 HADE 37
4. Lot No, Record	ed Plat	
requirements of P.A. 74, Michigan conformance with regulations and r. United States Department of the International in Board of Land Surveyors or by a	in a field survey on NOVEMBER, 1996 do hereby state that under P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in eles therefore as required in the current manual of survey instructions of the elor, Bureau of Land Management or by a decree of a Court of Law and for Decree of a Court of the Michigan	1 A B C D E F G H I J K L 2 6 5 4 3 2 1 3 4 7 8 9 10 11 12 5 6 10 17 16 15 14 13
,	s, all in the same town and range, may be recorded	8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
A Depointing of the con-		11 32 33 34 35 36
	ment and accessories and/or subsequent restoration:	RATIFIED BY PEER GROUP P.A. 345 OF 1990
Witness Corner to Meander Corner to Se	ections 6 and 31, T47/48N-R30W on the West side of Gibson Lake.	Lang & Bussine
W.C. M.C. B/C-13:	1846; W. A. John & Austin Burt D.S. marked a 4" Tamarack for l	DATE 11/4/960  Meander Comer. No witnesses established.
B. Description of corner evidence	1984; L.L.S. No. 30091 set a 1/2" x 18" capped rebar 4' from wat in: 12" Spruce N15"W 11.80'; 10" Spruce N55"W 16.35'; 10" 32.33'. Recorded in L.4R.C., Pg. 425.	ers edge on Township Line witnessed by masonry nails dead Spruce S85°W 21.97°; 14" White Pine S65°W
2. Description of connet evidence	e found and/or method applied in restoring or reestablishing corne	er;
W.C. M.C. B/C-13:	1996; ECI recovered capped rebar on West side of Gibson Lake aborecovered. The following measurements were taken to G.L.O. terra West "ascend hill ECI 149' -G.L.O. 137', "descend hill" ECI 10 acceptance of capped rebar as a careful and faithful reestablishment of 1600.25' and distance West is 1478.06'.	un calls: East "over lake" ECI 1565' -G.L.O. 1570';
C. Description of monument for co	orner and accessories established to perpetuate locating the position	on of the corner:
1996:	Replaced capped rebar with a 2-3/8" O.D. aluminum pipe capped with monument stamped to identify the corner set about 0.6' above grade. It yellow with B.T. tags attached. But blaze is scribed "B.T.". Three 19 a duplex nail with an orange washer stamped "ECI-30097" in the side of	bearing trees are face, nail & butt blazed and painted
•	abanes 2170 (1 1170)	26" White Pine S64"W 32.19";
Signed byK	Steel fence post with survey marker sign -North 1.0'.	STATE OF BUILDING
Surveyor's Michigan License No	Date 7-	SURVEYOR X
		ATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1965