

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

| Baraga<br>(County)                    | Located In:      | Corner Code # |
|---------------------------------------|------------------|---------------|
| 1. Public Land Survey                 | T R              |               |
|                                       | T R              |               |
|                                       | T R              |               |
| 2. Property Controlling<br>in Section | S 17 T 48N R 32W | 6             |
|                                       | S 8 T 48N R 32W  | 14            |
|                                       | S T R            |               |
| 3. Miscellaneous<br>Property in Sec.  | S T R            |               |
|                                       | S T R            |               |

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Stephan J. Szyszkoski, in a field survey on 6 05/31/2012  
14 09/19/2012 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(6-Section 17) Northeast 1/16 corner, Section 17. Not previously monumented.

(14-Sec. 8) South 1/16 corner between Sections 8 and 9. 1975 - Corner monumented in 1975 by  
K.L.Sackett RLS midway and on line between Section and Quarter corners. Set 1"IDx36" I.pipe with 4"  
alum. MDNR cap.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(6-Sec. 17) Established the position for the corner at the intersection of straight lines connecting  
opposite 1/16 corners. The position for the corner falls in swamp land and cannot be satisfactorily  
monumented. Established a WITNESS CORNER to the 1/16 corner, on the North 1/16 line of Section 17,  
79.00 ft. east of the corner position.

(14-Sec. 8) Found the 1975 monument in good condition, at record bearing and distance from the  
remaining witnesses of record, now all down, but 8.86' southerly of the position intended in 1975. I  
did not accept the monument as marking the corner position and I removed it. I established the  
position for the corner midway and on the Section line between Section corner 1325.59' south and  
Quarter corner 1325.59' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(6) Set 1"IDx32" I.pipe with 4" alum. MDNR cap  
for a WITNESS CORNER 79.00' east of the 1/16  
corner position and on the 1/16 line.  
Set measuring nail with MDNR tag in the side of:  
4" B.Spruce N30W 30.05' mrkd "WC BT"  
4" Balsam N03W 12.5' do  
6" Balsam N73E 12.45' do  
8" B.Spruce S44E 20.0' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

(14) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
9" Cherry N07E 14.55' mrkd "1/16S BT"  
4" Balsam S66E 2.25' do  
5" Balsam S09W 11.5' do  
10" Maple in clump S89W 18.85' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 09/19/2012

For the Michigan Department of Natural Resources, Forest Resources Division

