JOB NUMBER: 93300 SHEET NO. : 1-345

MARQUETTE (County)

For corners in

4. Lot No. _ 5. Private Claims _

expressed below:

COMMISSICIAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Located In:	Corner Code ##
T _{48N} R 25w T _{48N} R 25w	A-13
T 47N R 25W T 47N R 26W	A-1

File Number

4	Public Land Survey	T _{48N} R _{25W}	A-13	H 200 10
١.	rubiic Lailu Suivey		(A=13)	3 10 _
		T _{48N} R _{26W}	M-13	
		T 47N R 25W	A=1	-
	1	T 47N R 26W	M=1	
2.	Property Controlling	S T R		
	in Section	S T R		Liber 1 R.C. Page 242
3.	Miscellaneous	S T R		Register of Deeds Stamp &
	Property in Sec.	S T R		

1. GERALD W. CARLSON in a field survey on Saturday, December 4 . 193
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11

A. Description of original monument and accessories and/or subsequent restoration:

A-13: Section Corner common to Section 31, T48N-R25W; Section 6. T47N-R25W; Section 36, T48N-R26W; and Section 1. SW corner of Section 31 verified by bearing trees. This T47N-R26W.1845: William A. Burt's original survey notes describe the corner as a wood post referenced by: 24 * Hemlock N79W, 75 1 20* W.Pine S63E, 45 1

__ , Recorded Plat _

No date given - Cummings recorded survey indicates the distance North of this corner is listed at 2640, the distance East from this corner is listed at 2456.3. No date given - Marquette County Road Commision book indicates a pipe at corner of old fence. No corner accessories given. (See reverse side)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1993 - Found a P-K set from George Wilson's witnesses. Chipped asphalt out and found 1 1/2" iron pipe 1.10 ft. below surface of asphalt. Also found cap for 5/8" iron buried next to pipe with RLS #17618. Set a 3/4" rebar 18" long inside 1 1/2" diameter pipe in Payne & Dolan road. Set a Marquette County Survey Monument on top of 3/4" rebar in monument box. Tablet is 0.6 below surface of road. Distance North is 4.73 ft. short of Cummings, distance East measures 2.45 ft. short of Cummings. Peer group ratification 11-29-93.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1993 - Set 3/4" rebar 18" long inside 1 1/2" diameter pipe with Marquette County Survey Monument cap on top of 3/4" rebar stamped to identify the corner in a monument box in the black top of Payne & Dolan Road referenced by nails in:

8" Maple N62E 94.20 ft.

9* Spruce S33E 89.30 ft.

S53W 72.4 ft. Donnan witness

N88W 109.50 ft.

The power poles are the Southeasterly poles of the Northwesterly two group of three poles of three groups of three poles at a PI in the power line. Monument is 0.6 ft. below surface of the road. E OF MICHIE

Bk. 3, Pg. 140

FORM APPROVED BY MICHIGA

GERALD W. CARLSON SURVEYOR

E

The second second

Record No. 345

Part "A" Continued:

1972 - William Donnan found a 1 1/4" iron pipe

5" Maple	N70°E	50.89 ft.
12" Tamarack	S75°E	59.67 ft.
Power Pole	S51°W	72.54 ft.

This corner not recorded.

1976 - George Wilson recorded a old iron pipe with iron rod inside with RLS cap 17618 that lines up with an old fence line running easterly from corner referenced by:

Face of a power pole	S65°W	82.90 ft.
Face of a power pole	S10°W	85.90 ft.

L1 RC, Pg. 143