

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 50N R 28W	F5
	T 50N R 28W	G5
	T	
2. Property Controlling in Section	S T	
	S T	
	S T	
3. Miscellaneous Property in Sec.	S T	
	S T	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on F5 09/13/2012 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F5) Quarter corner common to Sections 9 and 16. 1992 - Reestablished by Paul N. Bressette PS, midway and on the Section line between Section corners. Set 1"ID I.pipe with 4" alum. MDNR cap. 18" W.Pine N61E 52.1', 8" Maple S01E 9.7', 7" Oak S35W 17.1', 8" Oak N15W 25.0'.

(G5) - Corner common to Sections 9-10-15-16. 1992 - Reestablished by proportionate measurement by Paul N. Bressette, PS 37270. Set 1"ID I.pipe with 4" alum. MDNR cap. 10" Sugar N39E 42.4', 15" W.Birch S40E 0.4', 6" Sugar S70W 4.8', 11" Sugar N08W 33.0'. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F5) Found the 1992 monument in good condition and at record bearing and distance from the remaining 1992 NBTs 8" Maple S02W and 8" Oak S38W, both in good condition. The other two NBTs are not present. The monument was found 6" below grade. Verified the position of the monument with respect to Section corners east and west and accepted same as a careful and faithful reestablishment of the position of the original corner.

(G5) Found the 1992 monument in good condition and at record bearing and distance from two remaining witnesses. The Sugar SW and the Sugar NE are in good condition. The W.Birch is dead, the Sugar NW is a stub. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F5) Fd. 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
8" Maple S02W 10.0' w/1992 scribing  
8" Oak S38W 17.55' w/old blazes (1992)  
4" Oak N03W 31.0' mrkd "1/4S NBT"  
18" Oak N51E 38.85' do  
Bearings are magnetic.

(G5) Found 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
7" Sugar S71W 5.1' overgrown blazes  
10" Sugar N40E 42.85' do  
6" Sugar N02E 44.95' mrkd "S10 NBT"  
6" Sugar S09E 10.1' "S15 NBT"  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 10/08/2012

For the Michigan Department of Natural Resources, Forest Resources Division

