

1999 DEC 22 AM 11:28

Patricia A. Monney
REGISTER OF DEEDS

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970For corners in
MARQUETTE
(County)

Located In:

Corner Code #

1. Public Land Survey

T 51N R 27W

G-4/5 M.C. #1

2. Property Controlling
in Section

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

LIBER **R2** PAGE 227

Register of Deeds Stamp & File Number

I, GERALD W. CARLSON, in a field survey on September 23, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G-4/5: Meander Corner common to Sections 9 and 10, T51N-R27W.

1846: William Ives' original subdivision survey notes describe the corner monument as a 10" Maple on sand bank 8' high at wide sand beach on Lake Superior. Referenced by: 12" Sugar West, 16 L

No Date: A survey map indicates the corner as an Iron. No accessories given.

No Date: A Survey Map indicates the corner as an Iron. No accessories given.

1959: A Survey Sketch of Burns Landing by R.D. Washburn, P.S. #6844, indicates a set stake 516' North of an Iron Pipe at the South-East corner of Government Lot 3.

(SEE REVERSE SIDE)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-4/5: 1999: Set the corner 1824.90' (GLO distance) on the projected line North between the section corner common to sections 9, 10, 15, and 16 and the 1/16 corner 1310.00' North of the section corner. No original evidence uncovered.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-4/5: 1999: Set a 2 3/8" O.D. aluminum pipe capped with a 3 1/4" diameter aluminum tablet Marquette County Survey Monument stamped to identify the corner. Monument is 0.3' below the sand surface.

Established new references:

7" Oak N22W, 13.20'

6" Maple S03W, 15.73'

5" Maple S22E, 13.38'

1 1/4" iron pipe N03E, 18.30' SCA Pt.#8065

1 1/4" iron pipe N07W, 4.61' SCA Pt.#8066

Green Steel Sign Post w/ Yellow Survey Marker Sign S50W, 1.36'

Note: Bearing trees have painted face, butt, and side nail blazes, d.h. measuring nails, and stamped B.T. Tags affixed.
Bk. 14, Pg. 131-134 T51N-R27W Corner Search Report 99100
Bk. 15, Pg. 1-2

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|---|----|---|----|---|----|---|----|---|----|---|---|
| 1 | | | | | | | | | | | | | |
| 2 | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | | |
| 13 | | | | | | | | | | | | | |

RATIFIED BY PEER GROUP
P.A. 245 OF 1999

DATE

10/11/99

Signed by Gerald W. CarlsonDate 12-8-99Surveyor's Michigan License No. 24589

G-4/5:
PART A CONTINUED:

SECTION

1973: A Certificate of Survey recorded by Gourdie, Fraser, and Associates, in L. 301, Deeds Pg. 267, indicates a monument set N00-25'-54"W, 1918.90' from the S.E. Corner of Section 9 and 608.67' from a found Iron at the S.E. corner of Government Lot 3. The monument is indicated as being +/- 85' South of the Shore of Lake Superior along the East Line of Section 9. No accessories or description of corner monument given.

1993/1995: A Certificate of Survey recorded by Dennis R. Destrampe, P.S. #18983, in L. 2, SM Pg. 89 (1993) and in L. 2, SM Pg. 134 (1995), indicates the Meander Corner as a found 1 1/4" Iron Pipe N00-27'-53"W, 519.23' from a found 1/2" Iron Pin at the S.E. Corner of Government Lot 3, and 1829.41' North of a found 3/4" Iron Pipe at the S.W. Corner of Section 10. Meander Corner referenced by:

| | | | | | |
|------------|-------|--------|----------|-------|--------|
| 10" Spruce | S66W, | 25.53' | 5" Maple | S08E, | 20.34' |
| 5" Oak | S24E, | 17.95' | 5" Oak | N37W, | 8.95' |