

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 17 T 52N R 29W	16
	S 17 T 52N R 29W	D6
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4			3		2		1
3													
4	7			8		9			10		11		12
5													
6	18			19		20			21		22		23
7													
8	19			20		21			22		23		24
9													
10	30			29		28			27		26		25
11													
12	31			32		33			34		35		36
13													

I, Stephan J. Szyszkoski, in a field survey on 16 11/09/2010
D6 11/09/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(16-Sec. 17) East 1/16 corner between Sections 17 and 20. Not established in the original survey.

(D6) Center of Section 17. 1991 - Established by G.C. Van Neste PS at the intersection of 1/4 lines.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(16-Sec. 17) Established the corner midway and on the Section line between Quarter corner 1324.01'
west and Section corner 1324.01' east.

(D6) Found a 5/8" dia rebar with plastic cap #27464 in accord with Mr. Van Neste's 1991 measurements.
Accepted same as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(16) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Cedar N03E 6.65' mrkd "1/16S BT"
18" Hemlock N34E 14.35' do
5" Sugar S58E 15.0' do
7" Y.Birch S66W 10.7' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(D6) Ed. 5/8" rebar with plastic cap #27464
Set measuring nail with MDNR tag in the side of:
14" Sugar S75E 10.25' mrkd "C1/4 BT"
10" Sugar S07W 14.6' do
4" Y.Birch N73W 18.5' do
6" Y.Birch N12W 16.6' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 02/02/2011

For the Michigan Department of Natural Resources and Environment, Forest Management Division

