## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette	Located In:	Corner Code #	2
(County)	_		
	727		
1. Public Land Survey	T R		
-	TR		
	T		
2. Property Controlling	S 18 T 52N R 29W	SMC N. of B6	
in Section	S 18 T 52N R 29W	B6	
	S T R 2944		
3. Miscellaneous	S T		
Property in Sec.	S T R	<del></del>	
respectly in sec.	·		
4. Lot No. Re	corded Plat		Register of Deeds Stamp & File Number
	Colded Flat		ABCDEFGRIJKIN
5. Private Claims			·
	SMC 11/1	0/2010	2 - 6 5 1 - 1 - 3 2 - 1 - 1 -
ı, Stephan J. Szyszkoski , i	in a field survey on B6 11/2	2/2010 do hereby state	3
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey			
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6			

a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(SMC N. of B6) Special Meander Corner on the N-S 1/4 line of Section 18 at Lake Superior. Not established in the original survey.

(B6) Center of Section 18. 1990 - Established by G.C.Van Neste PS at the intersection of 1/4 lines of Section 18.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(SMC) Established the corner on the N-S 1/4 line of Section 18 near the shore of Lake Superior. Said N-S 1/4 line was found previously established and monumented by G.C.Van Neste PS. The position for this corner is not necessarily at the ordinary high water mark of Lake Superior and this position is not intended to fix or limit any littoral or riparian rights.

(B6) Found a 5/8" dia. rebar with plastic cap #27464 in accord with Mr. Van Neste's measurements and at the intersection of 1/4 lines of Section 18. Accepted the monument as a careful and faithful determination of the position of the corner. Found a 4" dia. concrete monument N68W 29.3' distant which I did not accept as marking the position for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(SMC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 8" W.Spruce N75E 9.65' mrkd "SMC BT" 6" Maple S49E 13.4' do 14" Maple S24W 16.3' do 8" Maple N63W 7.2' do Found 5/8" rebar w/cap #27464 31.78' south and on the N-S 1/4 line of Sec. 18. Bearings are magnetic.

(B6) Fd. 5/8" rebar with plastic cap #27464 Set measuring nail with MDNR tag in the side of: 8" Maple N23E 19.9' mrkd "C1/4 BT" 6" Sugar S36E 18.35' do 13" Hemlock S72W 42.6' do 4" Maple N47W 11.5' do Set sq'd Cedar post adjacent. Bearings are magnetic.

Signed by Surveyor's Michigan License No. 33986

Date 02/02/2011

SZYSZKOSKI LAND

CAND \$

STEPHAN J

OF MICH,

<sub>IS</sub>SURVEYOR

For the Michigan Department of Natural Resources and Environment, Forest Manageme

16603 16606 FORM APPROVED BY MICHIGAN STATE BOARD

10

11

rsed Jan., 1983

Rervised Oct., 1995