LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Marquette (County)	_ Located In:	Corner Code #					
1. Public Land Survey	T 52N R 29W T 52N R 29W T R	A6 B7					
2. Property Controlling in Section	S T R S T R						
3. Miscellaneous Property in Sec.	S T R S T R		Posis	ter of Deeds	Stama 9 Ei	ilo Alexandres	
4. Lot No. , Red 5. Private Claims	corded Plat	2.	A B	C D E	F G H	I J K	LM
ı, Stephan J. Szyszkoski , ir		1/03/2010 do hereby state	3	5 -	4 3 	2-	1
above were in conformance with	regulations and rules therefore as req	er points mentioned in lines 1 and 2 juired in the current manual of survey	5	8-	9—10-	-13-	-12-
a Court of Law and /or that the o	corner points mentioned in lines 3, 4 a	f Land Management or by a decree of and 5 above were in conformance with see of a Court of Law; established,	7		-15-		13-
re-established, monumented, recover			9			-23-	24—
NOTE: Not more than 2 corners, all in the same town and range, may be recorded			10 30	29-1-2	27-	26	25-
THE REPORT OF THE PARTY OF THE			12 31	323	¹³ — 34	35	-36

A. Description of original monument and accessories and/or subsequent restoration:

(A6) Quarter corner common to Section 13 T52N-R30W, Baraga County and Section 18 T52N-R29W, Marquette County. 1985 - K.L.Sackett RLS remonumented the corner from an old 40" yellow birch found with axe marks and believed to be an original bearing tree. Set 1"IDx32" I.pipe with 4" alum. cap. 16" Hemlock N75E 3.0', 12" Hemlock S10E 17.2', 10" Sugar S50W 17.8'. 1990 - G.C.Van Neste RLS used this monument to control the subdivision of Section 18 T52N-R29W.

(B7) Quarter corner common to Sections 18-19. 1990 - Remonumented by G.C. Van Neste PS 2639.93' west of C7, 2843.07' east of A7, 2639.49' south of B6. This position was used to subdivide Section 18. Set 5/8" capped rebar. The undersigned does not know whether or not witnesses were taken in 1990.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A6) Found the 1985 monument in good condition and at record bearing and distance from the 1985 witnesses, all dead with scribing and measuring notch visible. The Y.Birch noted in the 1985 record was not found. Accepted the monument as the best available evidence of the position of the original corner.

(B7) Found a 5/8" dia. rebar with plastic cap #27464 2640.12' west of monumented C7 and 2639.50' south of monumented B6, in substantial accord with Mr. Van Neste's bearings and distances. Distance to A7 was not measured in this survey. I accepted the monument as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A6) Found 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 14" Maple N46E 19.25' mrkd "1/45 NBT" 7" Sugar S28W 11.75' do 7" Sugar S60W 21.7' do 16" Cedar N10W 43.3' do Set sq'd cedar post adjacent. Bearings are magnetic.

(B7) Fd. 5/8" rebar with plastic cap #27464 in a small mound of rock. Set measuring nail with MDNR tag in the side of: 17" Maple N70E 13.5' mrkd "1/4S NBT" old marks 10" Sugar S38E 6.9' mrkd "1/4S NBT" 8" Sugar S72W 9.9' do

18" Hemlock N51W 9.95' do

Bearings are magnetic.

Signed by 02/02/2011 Date Surveyor's Michigan Licénse No. 33986

SZYSZKOSKI LAND _{is}surveyor

CAND

STEPHAN J

MICH

For the Michigan Department of Natural Resources and Environment, Forest Manageme

16589 16590 FORM APPROVED BY MICHIGAN STATE BOARD

14, 1975 sed Jan., 1983 Rervised Oct., 1995