

FEB 11 1998

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 of
P.A. of 1996 On 12/13 1997
McLain RLS
Chairman

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T^{34N} R^{27W}

D/E-9

(007)

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

97 DEC 22 11:26
PAGE # 577, BK 5
MENOMINEE COUNTY
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

I, William Lenca, in a field survey on June 25, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	10		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by James H. Mullett - B.T.'s - Y. Pine, 8" - N75°E - 07 lks.; Y. Pine, 8" - S51°E - 12 lks. All original evidence for this corner has been destroyed by river erosion and ice jams.
- 1960: Plat of Survey by Robert Olsen shows a tie to this corner. A corner monument is indicated but is not described. The survey shows the corner as being on line with a fence.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 1-1/4 inch diameter iron pipe on the bank of the Menominee River and in line with an ancient fence to the East as shown in Robert Olsen's 1960 survey. Since the existing iron pipe was very close to the edge of the bank of the river, we set a new monument 4.95 feet East. This position fits existing lines of occupation, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 2" dia. Aluminum Pipe/3-1/4" dia. Alum cap stamped for corner location:

16" dia. Oak	4	N79°E	35.54 feet	Scr. NBT
N.W. Corner of House Foundation	1	S22°E	33.32 feet	
12" dia. White Pine	2	S40°W	23.14 feet	
24" dia. White Pine	3	N32°W	18.20 feet	
Metal Survey Sign Post		East	0.95 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Dec. 12, 1997

