

APR 06 1999

Approved by Menominee County
Land Survey Remonumentation
Peer Group Under Act 345 Of

P.A. Of 1990 On 12/30 1998
MEL DAVIS RLS
Chairman

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE

(County)

Located In:

Corner Code #

1. Public Land Survey

T35N R 27W

D-09

2. Property Controlling
in Section

S

T R

3. Miscellaneous
Property in Sec.

S

T R

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

RECEIVED FOR RECORD
99 JAN -6 AM 8:55
PAGE # 718 BKS
BARBARA MORRISON
REGISTER OF DEEDS
MENOMINEE, MI 49858

Register of Deeds Stamp & File Number

I, William Lenca, in a field survey on May 07, 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

A. Description of original monument and accessories and/or subsequent restoration:

- 1848: Original Survey by James H. Mullett - B.T.'s - Cedar, 6" - N45°W - 09 lks.; Cedar, 10" - S35°E - 12 lks. All original evidence for this corner has been destroyed by county road improvements.
- 1984: L.C.R.C. Number 603 by George B. Wilson states, "LOST CORNER: COUNTY ROAD" - Set 4" dia. Berntsen Road Monument. (to be set in spring) - Not found.
- 1984: Certified Survey Number 380 by George B. Wilson, RLS 17607, shows this corner as it relates to other corners in Section 29, T35N-R27W.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We found a railroad spike 1' North of the centerline of an East - West county road and in line with the centerline of a county road North - South. This location matches with ties to corners shown in Certified Survey No. 380. The position of the Railroad Spike has been continuously used by local surveyors for at least 14 years, fits well with existing lines of occupation, and is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	N37°E	40.79 feet	1' E. of Rd. Sign
8" dia. Cedar	S16°E	86.99 feet	Scr. NBT
4" dia. White Ash	S53°W	100.60 feet	Scr. NBT
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"	N33°W	53.41 feet	@ Sign Post
Metal Survey Sign Post	N33°W	54.4 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca

Date Dec. 22, 1998

Surveyor's Michigan License No. 26461

