

# SURVEY & REMONUMENTATION

FEB 11 1998

Approved by Menominee County  
Land Survey Remonumentation  
Peer Group Under Act 345 Of  
P.A. Of 1990 On 10/31 1997  
Mr. D. RLS  
Chairman

## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE  
(County)

Located in:

Corner Code #

1. Public Land Survey

T6N R 24W E/F-5

T R (004)

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

I, William Lenca, in a field survey on Sep. 04, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

1848: Original Survey by James H. Mullett - B.T.'s - Spruce, 8" - N30°W - 128 lks.; Birch, 10" - S61°W - 75 lks. All original evidence for this corner has been destroyed by shore erosion.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

We recovered a 1 inch hex head iron bolt at the base of a blazed 20 inch diameter White Birch with an ancient fence running E - W through the tree. We also found a 5/8" diameter iron rod with plastic identification cap (DAVIS - RLS 16906) at the 1/16 corner to the West, which falls on line between the iron bolt and the Southwest Corner of Section 9. We accepted the location of the iron bolt as the best available evidence of the position of the original corner, and replaced the iron bolt with a standard county monument as described in part "C" below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:  
Set 3/4" x 4' long aluminum rod 3-1/4" dia. Alum. cap stamped for corner:

10" dia. Cedar	N50°E	16.46 feet	Scr. NBT
20" dia. White Birch	East	3.13 feet	
10" dia. Cedar	S02°E	6.72 feet	Scr. NBT
12" dia. Cedar	N57°W	80.77 feet	Scr. NBT
Metal Survey Sign Post	North	0.9 feet	

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca  
Surveyor's Michigan License No. 26461

Date Sep. 05, 1997