

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MENOMINEE
(County)

Located In:

Corner Code #

1. Public Land Survey

T37N R 25W B03

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

I, William Lenca, in a field survey on Aug. 27, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- 1847: Original Survey (Twp Edy) by James H. Mullett - B.T.'s - Hemlock, 10" - S89°W - 19 lks.; White Birch, 14" - N82°E - 10 lks. All original evidence for this corner has been destroyed by county road improvements.
1899: Subdivision of Section 7, T37N-R25W by Albert Haas, County Surveyor, states "Original Government Corner found - 4 inch Cedar Post in center of Highway". No new B.T.'s given.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A railroad spike was found in the centerline of county roads running East - West and North fitting a single proportion position. The distance from the railroad spike West to the Northwest Corner of Section 7 (A-3) fits within 1 foot of Albert Haas' recorded measurement. We accepted the railroad spike as a careful and faithful reestablishment of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
Set 5/8" x 24" Iron Rod/3-1/4" dia. Alum. cap stamped for corner location in Monument Box:

5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"
5/8" x 24" Iron Rod/2" dia. Alum. cap marked "WITNESS MARKER"
9" dia. Elm
Metal Survey Sign Post
Nothing else nearby

N60°E 73.45 feet @ Cor. Fc. Post
S39°E 46.44 feet 1' S. of Tel. Box
S69°W 75.41 feet Scr. NBT
South 31.6 feet

NOTE: All bearings are magnetic bearings. All distances are measured with steel tape. Distances to trees are to nail in side of tree.

Signed by William Lenca
Surveyor's Michigan License No. 26461

Date Sep. 24, 1996

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2		6		5		4		3		2		1
3												
4		7		8		9		10		11		12
5												
6		18		17		16		15		14		13
7												
8		19		20		21		22		23		24
9												
10		30		29		28		27		26		25
11												
12		31		32		33		34		35		36
13												

