Approved by Menominee County
Land Survey Remonumentation
Poer Group Under Act 345 Of
1990 On 199

			et 74, Mich. P.A. 1			215
For corners in	i iiiig ixo	quironione or 7 k	1	•••	Chairman	
MENOMINEE	Landad Inc	Corner Code #	`		S 25	:27
(County)	Located In:	Corner Code #		₹ [™] 17		
• •,				\ 		REWED
1. Public Land Survey	T <u>37N</u> R_26W		- '	diameter and a second	記しまり	⇔
	TR_ T <u>38</u> R <u>26</u>	(E-13)				
	TR				1.	514
2. Property Controlling	s TR		_	* 13 		RESAU
in Section	s <u>TR</u>		_	2	25.08 25.09 26.09	graphics A.
3. Miscellaneous	S TR		-			
Property in Sec.	S TR		–	Register of D	Deeds Stamp & I	File Number
•						
4. Lot No, Record 5. Private Claims	led Plat			A B C D	F F G H	JKL
5. Private Claims				2 - 6 - 5 -	T 3	\[\] \.
(SAME AS E-13 T38N-R	26W)			3 1		
		. 40		·	9-10	1112
I, William Lenca, requirements of P.A. 74, Michigar	in a field survey on <u>No</u>	<u>nv 14</u> , 19 <u>95</u> do vis mentioned in lines	nereby state that under a 1 and 2 above were in	r 4 7 - 1 - 8 -	1 1	
conformance with requisitions and	rules therefore as required in th	le current manual of S	survey instructions of the	• 1		
United States Department of the in that the corner points mentioned in the corner points are considered in the corner points and corner points are considered in the corner p	iterior. Rureau of Land Manage	ement or by a decree (of a Court of Law and /o	f 61 8 17	1615	1413
Board of Land Surveyors of by	a Decree of a Court of Law	; established, re-est	ablished, monumented	, 7		
recovered, found as expressed bel	ow:			8 -1920-	2122	2324
NOTE: Not more than 2 come	ore all in the same town and	range, may be rec	orded	9		
on this certificate.	ers, and its the same town and	i iunigal may are see	•	10 -30 -29	28 27	2625
				11		
				12 31 32	33 34	3536
				13		
A. Description of original mor	nument and accessories ar	nd/or subsequent r	estoration:			
•						- # 1t
1848: Original Survey	(Twp. Bdy.) by James H.	Mullett - B.T.'s -	Hemlock, 12" - N32	2°W - 47 lks; Ceda	r, 8" - N590E -	15 lks.
All original evide	ence has been destroyed b	y farming activiti	es.	C Hen. Claden 9th 1	520011 06 lbg	A 11
1852: Original Survey	(Sec. Subd.) by Francis C has been destroyed by fa	oleman - B. i . s rming octivities	FIF, 10" - 572°E - 0	o iks, Ceuai, o -	330- W - 00 IVS.	ЛЦ
1963: L.C.R.C. No. 78'	7, Vol. 3 - recorded by C.	rinnig activities. C Linderen Sur	vev Chief Mich. St	ate Hwy Dept., state	es that he set a	l" iron pin
at an existing fer	nce corner. TIES: 7" Ced	I S25E - 14.56'	(gone); 4" Ced N	140W - 22.08' (foun	ıd); 5" Poplar -	N05E -
15.05' (found).					**	
•						
B. Description of corner evid	dence found and/or method	applied in restorr	ng or reestablishing c	orner:		
In a 1995 Survey in Section	on 5, T37N-R26W, we for	und a 1" diameter	x 32" long iron rod	I at the intersection	of ancient fence	es running
South - East & West, alor	ng with 2 of the B.T.'s esta	ablished by Lindg	ren as noted in part	"A". This corner p	position agrees v	well with
an original terrain call to	"swamp edge" 1 chain (6)	6 feet) East (recor	ded and measured).	This corner has be	een accepted an	d used by
local surveyors for at leas	t 32 years, and is accepted	i as the best avail	able evidence of the	position of the orig	gman comer.	
,						
					المعالمة للمنظون	amara
C. Description of monument	for corner and accessories	established to per	petuate locating the	position of the corne	T. JOHN TE	1164 B
Set 2" dia. Aluminum Pip	e/3-1/4" dia. Alum cap si	amped for corner	location:		A WILL	IAM *
0002 0000) W .	NCA :
7" dia. Cedar	N16 ⁰ E		Scr. NBT			VEYOR 1
12" dia. Tamarack	N77 ⁰ E		Scr. NBT			to
5" dia. Cedar	South	16.39 feet	Scr. NBT			5461
8" dia. Cedar	N70 ^O W		Scr. NBT		SON IFAIR	LAND SUPPLIED
Metal Survey Sign Po	st West	1.0 feet			ALTONO N	mornali
NOTE: All bearings are	magnetic bearings. All d	istances are meas	ured with a steel tar	e. Distances to tre	es are to nail in	side of
tree.						,
11m	/ -/-		5 .4.	Dec. 11, 1995		
Signed by	en Ames		Date			
Surveyor's Michigan License	No26461					