

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Menominee</u> (County)	Located In:	Corner Code \neq
1. Public Land Survey	T <u>40N</u> R <u>25W</u>	<u>C-8, A-7, C-7, B-7</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

I, Paul Bressette, in a field survey on April 29; May 6, 13; June 4, 1992, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- C-8. Quarter corner common to Sections 19 and 20.
- A-7. Section corner common to Sections 18, 19, 13, and 24. 1960, Billy D. Buckler, RLS. Set 1" iron pipe with brass cap. 7" Hard Maple, S36E, 19 Lks.; 7" Hard Maple N34W, 38 Lks.; 12" W. Ash, S78W, 44 Lks.
- C-7. Corner common to Sections 17, 18, 19, and 20. 1960, Billy D. Buckler, RLS. Set 5/8" X 24" iron pipe in centerline of road. No witnesses.
- B-7. Quarter corner common to Sections 18 and 19. 1960, Billy D. Buckler, RLS. Set 1" iron pipe with 4" brass cap. 8" tamarack, S68W, 43 Lks.; 7" Tamarack, N23E, 36 1/2 Lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- C-8. Found boat spike in centerline of gravel road and old fence line running west. Replaced boat spike with DNR monument.
- A-7. Found monument as described. No evidence of NBT's. Witnessed monument as found.
- C-7. Found iron pipe as described in centerline of road. Re-witnessed as found.
- B-7. Found monument and old tamarack BT, N42E. Witnessed monument as found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- | | | |
|--------------------------|-----------------------------|----------------------------|
| C-8. DNR Monument | A-7. Dept. Cons., Brass/Cap | C-7. 3/4" Iron Pipe |
| 8" Cedar, N75E, 30.5' | 10" Sugar, N19E, 39.3' | 7" Twin Sugar, N29E, 66.3' |
| 8" Tamarack, S50E, 30.7' | 8" Sugar, S82E, 15.85' | 5" Cherry, N87W, 21.9' |
| 5" Tamarack, N87W, 40.3' | 8" Sugar, S31E, 12.35' | 5" Apple, N75W, 26.45' |
| 7" Tamarack, N29W, 70.9' | 18" Hemlock, N42W, 2.0' | 6" Cherry, N12W, 75.9' |

- B-7. 1" Iron Pipe with 4" Brass Cap
- 8" Cherry, N20E, 27.1'
- 7" B. Spruce, S64E, 31.1'
- 5" Tamarack, S06W, 34.6'
- 6" Cedar, S50W, 46.8'

Signed by Paul R. Bressette Date 8-13-92

Surveyor's Michigan License No. 37270

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

