

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee

(County)

Located In:

Corner Code #

1. Public Land Survey

T 41N R 26W

F07

2. Property Controlling

S T R

n Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Jeremy J. Pipp, in a field survey on 8/13/2014 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

1. Description of original monument and accessories and/or subsequent restoration:

(F07) Quarter corner common to Sections 16 and 21. 1852: E.C. Martin, DS. Set quarter  
section post witnessed by Lynn 20 S40W 52 links (34.32'), Lynn 10 N60E 11 links  
(7.26'). No evidence of subsequent establishment.

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F07) No evidence of original survey. Slight drop corresponding to GLO call of "41.00  
Decend Hill course SW" (66 feet East); monument location would have to go over a chain  
south of MPOL position to make this a distinct call and would thus be too far south of  
lines between other previously monumented corners of record along the Township midline  
[1850 instructions]. Thus corner position reestablished by single proportionate  
measurement between the Southwest corner and the Southeast corner of Section 16. Position  
is accepted as a careful and faithful REESTABLISHMENT of the position of the original  
corner.

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F07) DNR monument  
8" Poplar N32E 20.50' (1/4S,NBT)  
6" Poplar S66E 4.93' (1/4S,NBT)  
7" Ironwood S29W 34.57' (1/4S,NBT)  
8" Poplar N55W 17.97' (1/4S,NBT)

All trees are blazed, scribed, painted,  
and signed. Measurements are to nail in  
side of tree, bearings are magnetic. A  
Metal sign post was set North 1.5 feet.

Signed by  
Surveyor's Michigan License No.



August 25, 2014

For the Michigan Department of Natural Resources, Forest Resources Division