

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Menominee	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 41N R 26W	G05
	T 41N R 26W	G06
	T R	
2. Property Controlling Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

3/17/2014
Jeremy J. Pipp, in a field survey on 3/17/2014 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(G05) Section corner common to Sections 9, 10, 15, and 16. 1852: E. C. Martin, DS. Set section corner post witnessed by Tamarack 10 S38W 35 links (23.10'), Tamarack 12 N30E 12 links (7.92'). 2014: Found 1" pipe with 4" Brass cap Department of Conservation monument NOT of record.

(G06) Quarter corner common to Sections 15 and 16. 1852: E. C. Martin, DS. Set Quarter section corner post witnessed by Tamarack 12 S38W 5 links (3.30'), Cedar 12 N40E 11 links (7.26'). No evidence of subsequent establishment.

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(G05) Accepted found MDNR Monument stamped for position. Mound NE corresponds to record OBT. Position is accepted as a careful and faithful PERPETUATION of the position of the original corner.

(G06) No evidence of original survey. Corner position reestablished by single proportionate measurement between the Northeast corner and the Southeast corner of Section 16. Position is accepted as a careful and faithful REESTABLISHMENT of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(G05) DNR monument	(G06) DNR monument
6" Tamarack N22E 24.22' (S 10,NBT)	9" Cedar N74E 13.04' (1/4S,NBT)
6" Cedar S62E 27.82' (S 15,NBT)	11" Cedar S24E 29.72' (1/4S,NBT)
7" Cedar S08W 13.37' (S 16,NBT)	7" Cedar S10W 35.47' (1/4S,NBT)
6" Cedar N52W 3.68' (S 9,NBT)	8" Tamarack N43W 9.64' (1/4S,NBT)
All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Metal sign post was set North 1.5 feet.	All trees are blazed, scribed, painted, and signed. Measurements are to nail in side of tree, bearings are magnetic. A Metal sign post was set North 1.5 feet.
Signed by _____	Signed by _____
Surveyor's Michigan License No. 50447	Date July 9, 2014

For the Michigan Department of Natural Resources



Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													