LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Montmorency (County)	Locate	d In				
1. Public Land Survey	T 29N T 29N	R 3E R 3E	A-9 A-11			
Property Controlling in Section	S T	- R R				
Miscellaneous Property in Section	S T T T T T T T T T T T T T T T T T T T	R		Registe	or of Deeds Stamp & F	file Number
4. Lot No: 5. Private Claims:	Recorded Plat:			A B C D	E F G H I	KLM
I, <u>Carl T. Kiiskila</u> , in a field survey on <u>September 21, 2010</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the				3 4 7 8 5	9 10 1	112
Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board o established, re-established	inagement or by a decre lines 3, 4 and 5 above to f Land Surveyors or b	e of a Court of L were in conforma y a Decree of	aw and/or that the ance with the rules a Court of Law;	7 8 19 20	-21222	3 24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.				10 30 29	28 27 27	25——25—

- A. Description of original monument and accessories and/or subsequent restoration:
- A-9 Section Corner comm. to sec.'s 19&30, T29N,R3E

1993 Montmorency Co. Remonumentation Liber – 12, Page 4 Donald Marlatt P.S. #18660 Found ½" Bar set by DelaMater in 1932. Placed Remon cap on found 1/2" bar.

Wits: N55°W 24" Oak 33.98' \$50°W 14" Oak 35.52' \$09°E 14" Oak 20.33' N87°E 12" Oak 30.00'

A-11 Section Corner comm. to sec.'s 30&31, T29N,R3E

1993 Montmorency Co. Remonumentation Liber - 12, Page 12 Donald Marlatt P.S. #18660 found concrete monument for corner Added Montmorency Remonumentation cap.

Wits: N43°E 18" Cedar 69.63" \$52°E 12" Basswood 43.65' \$60°W P. Pole 69.60' N60°W 6" Oak 35.08'

- B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:
- A-9 Section Corner comm. to sec.'s 19&30, T29N,R3E

A-11 Section Corner comm. to sec.'s 30&31, T29N,R3E

Found ½" bar fitting D. Marlatt witnesses with remonumentation cap removed. Drove 1" x 36" galvanized pipe with standard DNR cap over found 1/2" bar.

Found a 4" concrete monument with the top broken off. Straightened 1/2" bar and added P.S. cap #33981.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- A-9 Section Corner comm. to sec.'s 19&30, T29N,R3E

A-11 Section Corner comm. to sec.'s 30&31, T29N,R3E

1" x 36" galvanized pipe with standard DNR cap.

Wits: N77°E 30.07' to found N&T S side 13" R. Oak S19°E 20.38' to found N&T W side 14, 16 and 21" R. Oak S43°E 35.44' to found N&T E side 14" R. Oak N57°W 33.90' to found N&T E side 29" R. Oak N48°W 13.68' to set N&T SW side 6" W. Pine

Wits: N37°E 69.67' to found N&T SE side 20" Cedar S62°E 77.72' to set N&T N side 6" Ash N66°W 35.05' to set N&T S side 14" Oak S56°W 69.47' to found N&T NW side P. Pole Corner falls 6' West of North-South Road North-South Road and 5' North Of road to West

KIISKILA 12-20-10 SURVEYOR

Surveyor's Michigan License No.:

33981

33981 SURVED LAND SURVED FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971
Revised May 14, 1975
Revised Jan. 1983

OF MICHIGAN

CARL

LAND

No.