## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

	t mily requirement of rice is a more	1
For Corners In: Montmorency (County)	Located In Corner Code #	
1. Public Land Survey	T 29N R 3E C-1	
Property Controlling in Section	S T R R	
Miscellaneous     Property in Section	S	Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	*
		A & C D E F G H I J K L M
5. Private Claims:		2 - 6 - 5 - 4 - 3 - 2 - 1 - 1
I, <u>Carl T. Kiiskila</u> , in a field survey on <u>March 17, 2011</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law established, re-established, monumented, recovered, found as expressed below:		3 4 7 8 9 10 11 12 5 6 18 17 16 15 14 13 7 8 19 20 21 22 23 24 9
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.		10 30 29 28 27 26 25
		11
		12 3 3 3 3 3 3 3 3 3 3 3 3 5 3 6
		13
A. Description of original monument and accessories and/or subsequent restoration:		
C-1 – NW section corner, section 5, T29N,R03E		
<ul> <li>1960 – Department of Conservation Land Corner Record – Kenneth J. Ostling, P.S.#10068 – This corner was restored at record government measure from standard corner to Sections 31 and 32, T30N, R03E, by Forestry Division survey crew while making a survey in this area. Stumps in general area for possible government BT's, but they do not conform very well with government record. Unable to locate anything more conclusive. Corner to sections 31 and 32, T30N,R03E is 10 links west.</li> <li>9" Aspen S49°E 25½ links</li> <li>10" Aspen S89°W 78 links</li> </ul>		
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:		
C-1 – NW section corner, section 5, T29N,R03E		
Found Department of Conservation monument per 1960 Land Corner Record by Ostling. Accepted found D.O.C. monument as a careful and faithful reestablishment of the position of the original corner. Found no other evidence to dispute the location for the corner.		
	900	a:
	×	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:		
C-1 – NW section corner, section 5, T29N,R03E		
4"dia. stamped alum. ca	p on 1" galvanized pipe.	THE OF MICH.
Witnesses: S25°W 33.58' to set N&T on W side 5" B. Cherry N64°W 8.87' to set N&T on W side 5" B. Cherry S85°W 59.00' to set N&T on N side 6" B. Cherry S12°E 1.15' to set PK&T on E side 6"x 6' cedar guard post N42°W 13.82' to fd. N&T#18660 on NE side 12" Aspen S89°W 6.56' fd. DOC, mon. (S.C.) SW corner sec. 32, T30N,R3E Set blue Carsonite post 1' North		

Surveyor's Michigan License No.:

33981

4-27-11