

SURVEY & REMONUMENTATION

JAN 22 2001

Montmorency County Remonumentation

Liber 00012 Page 0419

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY

(County)

Located In: BRILEY

Corner Code #

1. Public Land Survey

T_{30N} R_{2E} C-6

T₁ R₁

T₂ R₂

T₃ R₃

2. Property Controlling in Section

S₁ T₁ R₁

S₂ T₂ R₂

3. Miscellaneous

S₃ T₃ R₃

Property in Sec.

S₄ T₄ R₄

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

11-13-2000 13:32:07

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, FREDERICK J. KING, in a field survey on MARCH 21, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

C-6 - 1/4 CORNER COMMON TO SECTIONS 17 & 18

June 1840 - Orig Post set by Lewis Clason, DS - (1)N42°W-34 lks (22.44') 9" Beech (2)S55°E-25 lks (16.50') 15" Beech -Pg 45

1941 - Frank Smith, PS#754 - Set 2 1/2" Conc Mon (3)EAST-33.0'-4" Conc Mkr (4)WEST-33.0'-4" Conc Mkr. - Info from L.G. Beauregard, PS#18654

May 1974 - Act 132 by L.G.Beauregard, PS#18654 (Surveyor for Scott Eng)-Rec L.1, Pgs 538 1/2 & 539 - Fnd F.Smith 2 1/2" Conc Mo Fnd F.Smith 4" Conc Mkr - 33.0' East (#3) & (#4) WEST

Sept 1989 - Act 132 by F.J.King, PS#25852 - Rec L.3, Pg 521 - Fnd Rec Mon - In Line Fnc to West - No Witnesses

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-6 - 1/4 CORNER COMMON TO SECTIONS 17 & 18

Fnd 4" Conc Mon (Rec. as 2 1/2")

Witnesses - Fnd Rec. 3 & 4



THIS CORNER APPROVED BY COUNTY PEER REVIEW ON JULY 18, 2000, AS THE BEST AVAILABLE EVIDENCE OF THE RE-ESTABLISHMENT OF THE ORIGINAL CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-6 - 1/4 CORNER COMMON TO SECTIONS 17 & 18

Placed 3 1/4" Aluminum Montmorency County Re-Mon Cap on Fnd 4" Conc Mon - Set Treated 2"x4" Alongside.

Corner is ±10' W of C.L. N-S 2-track road (Beltz Rd.)

NORTH - 66.76' - Set S&T - E side 8" Maple

(Wit#3) - EAST - ±33' - Fnd 4" Conc Mon (Has been hit, tipped & broken)

S50°W - 20.67' - Set S&T - NW side 12" Maple

(Wit#4) - WEST - 32.81' (R-33.0') - Fnd 4" Conc Mon

N75°W - 14.89' - Set S&T - NE side 10" Maple

Typical Wit Set = 16-D Spk & Plastic ID Tag #25852

Signed by

Frederick J. King

Date October 30, 2000

Surveyor's Michigan License No. 25852