

**SURVEY &
REMONUMENTATION**

JAN 22 2001

Montmorency County Remonumentation

Liber **00012** Page **0442**

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MONTMORENCY

(County)

Located in:
BRILEY TWP.

Corner Code #

1. Public Land Survey

T 30 N R 2 E

E-2

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

STATE OF MICHIGAN
MONTMORENCY COUNTY
Recorded & Filed

12-05-2000 10:06:31

TERESA WALKER
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L
1												
2	6			5		4		3		2		1
3												
4	7			8		9		10		11		12
5												
6	18			17		16		15		14		13
7												
8	19			20		21		22		23		24
9												
10	30			29		28		27		26		25
11												
12	31			32		33		34		35		36
13												

I, DONALD E MARLATT, in a field survey on MAY, 2000, 19 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-2 1/4 CORNER COMMON TO SECTIONS 4 & 5.

G.L.O. CORNER SET BY LEWIS CLASON IN APRIL 1840. Hd MAPLE 18" S50°E 44 L., BEECH 8" N29°W 30.
FOUND NO EVIDENCE OR RECORD OF CORNER.

APPROVED BY
PEER GROUP

JUL 18 00

L.B.B.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-2 1/4 CORNER COMMON TO SECTIONS 4 & 5.

NO EVIDENCE OF CORNER FOUND.

SET CONC. MONUMENT AND REMON. CAP SINGLE PROPORTION TO GLO DISTANCE.

CORNER FALLS AT THE NORTH EDGE OF TRAIL ROAD E & W.

DISTANCE FOR THE TOTAL LINE MATCHED MSHD SURVEY CO-ORDINATE COMPUTATIONS IN FEB. 1968.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-2 1/4 CORNER COMMON TO SECTIONS 4 & 5.

SET CONC. MONUMENT AND REMON CAP.

N26°W 16"MAPLE 5.95'

S45°E 14"MAPLE 26.70'

S40°W 13"MAPLE 18.56'

N70°W 14"MAPLE 20.44'

WITNESSES MARKED WITH 40 PENNY SPIKES AND P.S. TAGS #18660

APPROVED BY PEER GROUP JULY 18, 2000 AS THE BEST AVAILABLE EVIDENCE OF THE RE-ESTABLISHMENT OF THE ORIGINAL CORNER.

Signed by Donald E Marlatt

Surveyor's Michigan License No. 18660

Date 12/4/2000

