## LAND CORNER RECORDATION CERTIFICATE

	i iiiig itequii	ement of Act 74, Mich.	. PA 1970
For Corners In: Montmorency (County)	Located In Vienna	Corner Code #	
1. Public Land Survey	Twp. T R		
2. Property Controlling in Section	S 24 T 32N R 3E S 24 T 32N R 3E	3 5	
Miscellaneous     Property in Section	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:		A B C D E F G H I J K L M
5. Private Claims:			2 6 5 4 3 2 1
I, Carl T. Kliskila, in a field survey on February.17 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			8 13 20 21 22 23 24 3
NOTE: Not more than 2 corners, all in the same town and be recorded on this certificate.		and range, may	10 30 29 28 27 26 25 11 12 31 32 33 34 35 38 13
			13
A. Description of original monument and accessories and/or subsequent restoration:			
<u>3</u> – N 1/16 Corner comm. to sec.'s 23&34, T32N,R3E <u>5</u> – CN 1/16 Corner, Section 24, T32N,R3E			
Survey, unrecorded – Donald E. Marlatt, P.S.#18660 – Set ½" rod and cap.			urvey, unrecorded – Donald E. Marlatt, 660 – Set ½" rod and cap.

- B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:
- 3 N 1/16 Corner comm. to sec.'s 23&34, T32N,R3E

5 - CN 1/16 Corner, Section 24, T32N,R3E

Found ½"CIR#18660 per unrecorded survey by Marlatt. E-W single strand fence running 16.5' South of corner. Found no other evidence to dispute the location of the corner. Accepted found 1/2" CIR as the best available evidence for the position of the comer.

Found 1/2"CIR#18660 per unrecorded survey by Marlatt. Corner falls 21' South of a fence post corner w/single strand wire running West and South. Found no other evidence to dispute the location of the corner. Accepted found 1/2" CIR as the best available evidence for the position of the corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 3 N 1/16 Corner comm. to sec.'s 23&34, T32N,R3E

5 - CN 1/16 Corner, Section 24, T32N,R3E

Found 1/2"CIR#18660.

'Wit: \*S22°E 8.44' to fd. nail on NW side 15" R. Oak \*S07°W 27.75' to fd. nail on E side 10" R. Oak \*N85°W 19.64' to fd. nail on N side 12" R. Oak \*N33°W 3.91' to fd. nail on SW side 4" Maple

Found 1/2"CIR#18660.

Set Blue Carsonite post w/location tag 2' North.

Wit: N41°E 47.92' to set N&T on NW side 12" B. Fir \*S87°E 5.96' to fd. nail on S side 6" R. Maple S25°W 23.94' to set N&T on W side 4" B. Fir \*N34°W 8.81' to fd. nail on S side 6" R. Maple \*N09°E 13.59' to fd. nail on W side 5" Poplar Set Blue Carsonite post w/location tag 1' North.

\* Previous recorded witness.

จ

\* Previous recorded witness.

Surveyor's Michigan License No.:

33981

OF MICHIGAN CARL KIISKILA LAND SURVEYOR No. 33981 SURVEY