SUMWEY 4 -EMONUME

MAY 28 1897.

1996 Newaygo County Remonumentation Project

NEWAYGO-COUNTY-REGISTER OF DEEDS LINDA M. BROWN

COMMI

LAND CORNER RECORDATION CERTIFICATE FILING REQUIREMENT of Act 74, Mich. P.A. 1970 '97 FEB 12 PM 4 45

			1714 1070	_	•	
For corners in Newaygo (County)	Located in:	Corner Code #		Linda?	n. Brou	المعادة
Public Land Survey Property Controlling in Section	T 16N R 13W T R T R T R T R T R T R T R T R T R T R	E-9	· VOL. 2	PAGE	43	
Miscellaneous Property in Sec.	STR STR	: Rec	gister of Deeds	Stamp & File	Number	_
4. Lot No, Reco 5. Private Claims	rded Plat		A B C	DEFO	нтэк	L M
I, Norman L. Ochs do hereby certify that under requirements mentioned in lines 1 and 2 therefore as required in the curroperatment of the Interior, Bure Law and/or that the corner po conformance with the rules of Decree of a Court of Law; estable recovered, found as expressed by	corners, all in the same to	of 1970, the comer guiations and rules the United States ecree of a Court of 5 above were in curveyors or by a d, re-monumented,	11		-10 11	
Northwest Corner, Section	n 28, Lilley Township, Newa	lygo County, Michigan	13			

A. DESCRIPTION OF ORIGINAL MONUMENT AND ACCESSORIES AND/OR SUBSEQUENT RESTORATION:

G.L.O. Thomas Whelpley Resurvey 1856 24" White Pine N31°W 22 Links (14.52')#1 14" White Pine S74½°W 19 Links (12.54')#2 12" White Pine S691/2°E 35 Links (23.1")#3

Survey Notes by George H. Johnson R.L.S. #504 1929 Information from LCRC #176 Black Oak Southwest 44.8' #4 10" Black Oak Northwest 82.5' #5

Glen S. Hackbardt R.L.S. #25844 Survey Recorded in Series O Number 8804 December 17, 1983 Found Concrete Monument 4" Oak S60°W 15.9' #8 8" Oak N43°W 48.9' #9 22" Oak S10°W 36.0' #11 Cedar Post North 1.6' #10

Norman L. Ochs, County Representative.

Robert A. Griffin R.L.S. #13584 LCRC #176 July 29, 1965 Found 4" Square cedar stake (rotted) at the intersection of old (50± years) fences North, South and West removed and set a 5" Square reinforced concrete post 5 feet long with 3" diameter brass disk.

Northeast Corner, Concrete Block Cabin (14' X16') S18°E 179.28' #6
10" Red Oak S20°W 45.70' #7
3" White Oak S60°W 15.85' #8
6" White Oak N43°W 48.96' #9 6" X 7' Cedar Post North 1.6' #10 Found stump #1

B. DESCRIPTION OF CORNER EVIDENCE FOUND AND/OR METHOD APPLIED IN RESTORING OR REESTABLISHING CORNER:

Found Robert A. Griffin's Concrete Monument with brass disk and the centerline of the trail road is 10 feet South and the centerline of trail road going North is 54 feet East and in fence line on ground going South and in fence line on ground going North and in fence line on ground going West and the condition of the recorded witnesses are: #1 found stump, #2 thru #5 gone, #6 good condition, #7 gone, #8 and #9 good condition, #10 on ground, found bottom 1.6' North, #11 good condition.

C. DESCRIPTION OF MONUMENT FOR CORNER AND ACCESSORIES ESTABLISHED TO PERPETUATE LOCATING THE POSITION OF THE CORNER:

Accepted Robert A. Griffin's Concrete Monument with brass disk as a substantial marker for the section corner and is accepted as a careful and faithful perpetuation of the original corner.

24" Pine Stump N31°W 14.52' to center #1 Northeast Corner Block Cabln S15°E 179.34' #6 6" White Oak S65°W 15.85' Found spike in South side of tree. #8 12" White Oak N40°W 48.96' Found spike in East side of tree. #9 22" Black Oak S18°W 36.00' Found spike in Northwest side of tree. 28" Black Oak South 47.60' Found spike in East side of tree. 24" Black Oak S22"W 35.99' Found spike in Westerly side of tree. Signed by Norman L. Ochs Surveyor's Michigan License No. 22439	Date <u>November 30, 1996</u>	NORMAN L. OCHS LAND SURVEYOR 22439
Approved by Peer Review Group On	Form approved by Michigan State Board	of Land Surveyors, Jan 28, 1971 Revised May 14, 1975
Norman L. Ochs, County Representative		Revised Jan., 1983