LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

Ogemaw (County)	Located In	Corner Code #	
 Public Land Survey Property Controlling in Section Miscellaneous Property in Section 	T 23N R 2E T 23N R 2E S T R S T R S T R S T R	F-11 G-11	Register of Deeds Stamp & File Number
4. Lot No: Recorded Plat: 5. Private Claims:			A B C D E F G H I J K L M
requirements of PA 74, M and 2 above were in confi the current manual of su interior, Bureau of Land M corner points mentioned in of the Michigan Board of	I survey on November 24, 2008 do helichigan PA of 1970, the corner points ormance with regulations and rules the rvey instructions of the United States anagement or by a decree of a Court of lines 3, 4 and 5 above were in confort Land Surveyors or by a Decree d, monumented, recovered, found as extending the property of the conformation of the c	mentioned in lines 1 erefore as required in s Department of the of Law and/or that the mance with the rules of a Court of Law;	3 4 - 7 - 8 - 9 - 10 - 11 - 12 - 5 6 - 18 - 17 - 16 - 15 - 14 - 13 - 7 8 - 19 - 20 - 21 - 22 - 23 - 24 - 9
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			10 30 29 28 27 26 25

- A. Description of original monument and accessories and/or subsequent restoration:
- F-11 GLO -James H. Mullett D.S. 1846

Set Qr. Section Post

Wit: Aspen 3 S70°W 56 links

No other near.

MDNR Survey - K.J. Ostling P.S.#10068 - 1978 -Set Corner in old N-S fence in line with section Corners.

Wits: 8" R.Pine S45°E 26.2'

4" R.Pine S35°W 48.5'

MDNR Survey - Carl T. Kiiskila P.S.#33981 - 1998-

Found DNR monument.

Wits: Oak 17" N19°E 6.62' R.Pine 11" S40°E 26.51'

R.Pine 7" S40°W 48.59'

Oak 5" N70°W 19.60'

G-11 GLO - J.H. Mullett D.S. 1846

Set Post for corner. Sec. 27,28,33&34

Wits: B. Oak 6 S70°E 36 links

B. Oak 8" N52°W 75 links

MDNR Survey - K.J. Ostling P.S.#10068 - 1978 -Fd. 3/4" pipe, fitting corners east and west.

Set DNR monument.

Wits: 10" Oak N30°W 14.1'

6" Oak N75°W 20.9'

OF MICHIGAN CARL CIISKILA LAND SURVEYOR 33981 NO ED LAND SURV

- B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:
- F-11 Revisited corner during traverse around section 28 and found monument to be gone. Area had seemed to be disturbed. Blue Carsonite post was destroyed and hole dug where monument was previously set. Reset new monument off of witnesses per DNR surveys. Accepted corner as a careful and faithful reestablishment of the position of the original corner.
- G-11 Found stamped 4" aluminum DOC monument per K.J. Ostling survey. Found fence going south and east from corner. Found no other evidence to dispute the location for the corner. Accepted found DOC monument as the best available evidence for the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-11 Stamped 4" Aluminum DNR cap on 1"x36" galv. pipe Wit: S40°W 48.58' to fd. nail on N side 8" Red Pine

N67°W 19.61' to fd. nail on NE side 6" Red Oak N20°E 6.61' to fd. nail on NW side 18" Red Oak S42°E 26.51' to fd. nail on N side 13" Red Pine

Set Blue Carsonite Post 1' North

G-11 Stamped 4" aluminum DOC monument on 1" galvanized pipe.

Wits: S75°W 8.48' to set N&T on S. side 6" W.Pine N23°W 15.47' to set N&T on E. side 4" Oak N51°E 5.87' to set N&T on SE. side 17" Oak S35°E 30.80' to set N&T on SW. side 14" Oak

Set Blue Carsonite Post 1' North

Signed by: Surveyor's Michigan License No.: 33981

Date: