

OTSEGO COUNTY REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970  
South Charlton Township

For corners in

Otsego

(County)

Located In:

Corner Code #

1. Public Land Survey

T 29N R 1W

E-7

T      R     

T      R     

T      R     

2. Property Controlling  
in Section

S      T      R     

S      T      R     

3. Miscellaneous  
Property in Sec.

S      T      R     

S      T      R     

4. Lot No.         , Recorded Plat         

5. Private Claims         

Register of Deeds Stamp & File Number

I, Carl T. Kiiskila, in a field survey on September 6, 2007 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

**NOTE:** Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

**A. Description of original monument and accessories and/or subsequent restoration:**

E-7 1856 GLO H. Mellen set post at corner of sections 16, 17, 20 and 21.

Wit.: Sp. Pine 7" N67°E 14 links

Sp. Pine 6" N48°E 65 links

County Surveyor's Book 2, Page 556, 1933 G. F. DeLaMater found both Government B's and P. 1 1/2" gas pipe in corner.

Wit.: Y. Pine 10" N25°E 188.3'

Y. Pine 14" S80°E 109.9'

1959 Department of Conservation Corner Record, K. J. Ostling RLS #10068 found 1 1/2" gas pipe at corner.

Wit.: J. Pine 8" N2 1/2°W 75 links (49.5')

J. Pine 8" N66°E 58 links (38.3')

R. Pine 20" S80°E 167 links (110.2')

**B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:**

E-7 Found a 1" pipe with broken brass cap.

Wit.: 24" R. Pine S73°E 110.3'

Found nail & tag 8" Twin J. Pine S04°E 47.27'

Found nail 8" J. Pine stub S25°W 7.76'

**C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:**

E-7 Accepted found DNR Monument as a perpetuation of the original government corner location replaced the broken DNR cap with a new cap.

Wit: Set nail & tag 10" J. Pine N81°E 85.75'

Found nail & tag 8" Twin J. Pine S04°E 47.27'

Set nail & tag 7" J. Pine N66°W 67.72'

Set nail & tag 7" J. Pine N39°E 21.89'

Found nail 8" J. Pine stub S25°W 7.76'

Set nail & tag 24" R. Pine S73°E 110.30'

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by

Carl T. Kiiskila

Date

10/8/07

Surveyor's Michigan License No. 33981