

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:
OTSEGO
(County)

Located In

Corner Code #

1. Public Land Survey	T	R	
	T	R	
2. Property Controlling in Section	S 32	T 32N	R 1W 9
	S 32	T 32N	R 1W 13
3. Miscellaneous Property in Section	S	T	R
	S	T	R

4. Lot No: Recorded Plat:

5. Private Claims:

I, Carl T. Kiiskila, in a field survey on January 5, 2010 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

9 CE 1/16 Corner, Section 32, T32N,R1W

None

13 SE 1/16 Corner Section 32, T32N,R1W

1936 - County Surveyor Record - Field notes - George F. DeLaMater,
P.S.#2674 - Set 1/2"x36" bar.
Y.Pine 6" S82°E 41.0'
Y.Pine 4" S11°E 31.7'

B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:

9 CE 1/16 Corner, Section 32, T32N,R1W

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Found no other evidence to dispute the location for the corner.

13 SE 1/16 Corner Section 32, T32N,R1W

Set stamped 2" dia. aluminum cap on 5/8"x34" rebar per standard BLM procedure. Found 1/2" bar S64°E 4.58' (probably DeLaMater's). Did not accept found bar. Found no other evidence to dispute the location for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

9 CE 1/16 Corner, Section 32, T32N,R1W

Stamped 2" dia. aluminum cap on 5/8"x34" rebar.

Wit: N68°E 32.39' to set N&T on SE side twin 16"x20" R.Oak
S27°E 15.40' to set N&T on SW side 10" R.Pine
S42°W 51.15' to set N&T on SE side 9" R.Pine
N88°W 7.14' to set N&T on S side 14" R.Pine
Set Blue Carsonite Post w/location tag 1' North

13 SE 1/16 Corner Section 32, T32N,R1W

Stamped 2" dia. aluminum cap on 5/8"x34" rebar.

Wit: N18°E 27.65' to set N&T on W side 18" R.Pine
N71°E 29.94' to set N&T on N side 14" R.Oak
S64°E 4.58' to fd. 1/2" bar w/cedar grd. post
S08°E 7.91' to set N&T on W side 17" R.Pine
N76°W 35.42' to set N&T on N side 16" R.Pine
Set Blue Carsonite Post w/location tag 1' North

Carl T. Kiiskila

Surveyor's Michigan License No.: 33981



10-26-10