

# SURVEY & REMONUMENTATION

FEB 27 1998

## SECTION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

97 OCT 30 AM 10:59

For corners in

<u>Ottawa</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>7N</u> R <u>16W</u>	H-2 <u>other #1</u>
	T _____ R _____	Center Section B
	T _____ R _____	Grand Haven Twp
2. Property Controlling in Section	S _____ T _____ R _____	
	S _____ T _____ R _____	
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	
	S _____ T _____ R _____	

*Delena Gant*  
Register of Deeds  
Ottawa County, MI

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, THOMAS E. JOINER in a field survey on 7-28- 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

H-2 H-2 has been reset and witnessed as part of the Ottawa County road reconstruction program and has not been approved by the Ottawa County Peer Group as the correct corner. There are currently two corners at this location see L.C.R.C. H-2 #2

Liber 2, Page 421  
11-29-73  
Found concrete monument  
SW 35.70 20" Maple  
WSW 17.78 6" Maple  
NW 37.07 30" Pine  
Unable to verify corner and witnesses

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-2 Found angle iron, set 36" steel bar in monument box



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-2 36" Steel bar

Nail in SE side 7" Red Pine  
Nail in S. side Power Pole  
SE garage corner of House #16405 Sleeper St  
36" steel bar in monument box  
Capped Iron  
3 feet South of center line 6 feet west of line to North

AZ 46° 58.44  
AZ 303° 47.07  
AZ 344° 154.32  
AZ 51° 16.89  
AZ 37° 54.54

\$ 9.00 CORNER  
\$ 1.00 PHOTO

Signed by Thomas E. Joiner Date 9-15-97  
Surveyor's Michigan License No. 18435