

**LAND CORNER RECORDATION CERTIFICATE**  
**Filing Requirement of Act 74, Mich. P.A. 1970**

For corners in

Ontonagon

(County)

Located in:

Corner Code #

1. Public Land Survey

T 46N R 39W

K2

T R

T R

T R

T R

2. Property Controlling  
in Section

S T

T R

S T

T R

3. Miscellaneous  
Property in Sec.

S T

T R

S T

T R

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

Sep 23 1997

I, Stephan J. Szyszkoski, in a field survey on \_\_\_\_\_, 19\_\_\_\_ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		16		17		18		19		20		21	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

(K2) Quarter corner common to Sections 1-2. Corner established in 1851 by Z.B. Searles: "Set Quarter Section post. W. Pine 8 S15E 5, do 10 N65W 13". Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K2) Original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. There are several old W. Pine stumps in the corner area. One, located about 20' south of the position monumented, shows an axe mark and evidence of an old face. However, I do not believe that it is an original BT. Of all the W. Pine remains recovered, no two stumps correspond to the original record. I judge the corner to be lost and reestablish the corner 40 chains, proportionate to the original record, north of the monumented K3 and on a line of mean true bearing between K1 and K3. Distances north and south to these corners, measured by GPS observations, were determined to be 2698.62' and 2650.24', respectively. At the position for the corner, I placed a 1" I.D. x 32" iron pipe capped with a 4" dia. cast aluminum MDNR tablet, appropriately stamped. Corner placed and witnessed by D. Laapela and B. Wheeler, Baraga District Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K2) Set 1" pipe with 4" MDNR cap.

Blazed and scribed the following:

4" Maple S67W 28.0' "1/4S NBT"

4" Maple N25W 45.4' "1/4S NBT"

5" Maple N06E 23.2' "1/4S NBT"

5" Maple S19E 48.1' "1/4S NBT"

Placed a squared maple post adjacent.

Bearings are magnetic. Distances to notch in lower blaze.



Signed by

*Stephan J. Szyszkoski*

Date

2/18/98

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources - Forest Management Division