

OCT 3 0 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

ONTONAGON

(County)

Located In:

Corner Code #

1. Public Land Survey

T48N R39W

K-5

T R

T R

T R

T R

2. Property Controlling
in Section

S

T R

S

T R

3. Miscellaneous
Property in Sec.

S

T R

S

T R

JUDITH D. ROEHM

06/12/97

Ontonagon County

09:46

LC 4/ 273 JUT

Fee:

9.00

Page 1 of 1

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

Section Corner common to Sections 11, 12, 13 & 14, T48N R39W.

I, Earl W. Applekamp, in a field survey on May 16, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Artemas Curtis, U.S. Deputy Surveyor, September 22, 1851. Set Wood Post.

ORIGINAL BEARING TREES:

Henlock 14" N55°W 22.44 feet

Henlock 12" S80°E 19.14 feet

PEER GROUP APPROVED

COUNTY REPRESENTATIVE

6-10-97

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Corner position falls at the intersection of a gravel and blacktop county road. Farming is being performed in 3 directions. There was nothing found in the road with the metal detector. The intersections of the two roads in conformance with the corners in four directions. I re-established the corner in the centerline of the intersection of the two roads.

Research on file with the Ontonagon County Remonumentation Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 5/8X24" rebar with a 3" stamped cap 2" below top of blacktop. I established a reference monument, a 2 1/2"X30" aluminum pipe with a 3" cap stamped to read: County Remonumentation, T48N R39W, R.M., S11, S12, S13, S14, 1997, P.S. 17610. I established 3 other reference objects.

Power Pole N35°W 38.08 feet - 5" Aspen S40°E 58.57 feet

REF. MON. N41°E 47.61 feet - Nail in 12"X6" cut off

- P. Pole S36°W 46.80 feet

Signed by Earl W. ApplekampDate May 27, 1997Surveyor's Michigan License No. 17610