SUMPLY & REMONUMENTATION

JUDITH D. ROEHM Ontonason County 4/ 51 JEM 05/09/96

14:24 9.00

Fee: Page 1 of 1

DEC 1 6 1996

Property in Sec.

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in COMMIS	SION	ing Requirement of Act 7-
ONTONAGON (County)	Located In:	Corner Code #
1. Public Land Survey	T <u>48N</u> R T R T R T R	40W K-9
2. Property Controlling in Section	S TR S TR	


Register of Deeds Stamp & File Number

_, Recorded Plat 4. Lot No. 5. Private Claims

Section Corner common to Sections 23, 24, 25, & 26, T48N R40W.

[Earl W. Applekamp in a field survey on April 18, 1996 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Corner established by J. Wells Burt, U.S. Deputy Survyeor, May 1851. Set Wood Post.

ORIGINAL BEARING TREES:

30" S23°E 19 links White Pine 20" White Pine N66°W 40 links PEER GROUP APPROVED polikano 5-07-96 HERESEMTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

At the apparent corner position I found a 1" iron pin in a monument box in the pavement on Highway M-28. This corner has been in since at least 1963. It is at the intersection of two major roads. The corner position is in general agreement with the original GLO field notes. This 1" iron pin has been used for numerous surveys in the area. I accepted the position as being the only logical position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

At the corner position is a 1" iron pin in a monument box in the parameter of Highway M-28. I set two reference monument pipe with a 21" corner by the parameter of the parameter pipe with a 21" corner by the parameter of the parameter pipe with a 21" corner by the parameter of t At the corner position is a 1" iron pin in a monument box in the pavement of Highway M-28. I set two reference monuments which are 2½"X30" aluminum pipe with a 3½" cap stamped to read: County Remonumentation, RM, S23, S24 NO. S25, S26, T48N R40W, 1996, P.S. 17610. In addition to the reference monuments I established two other reference objects.

	GARIAN,
5.10'	
2.52'	

REF. MON.

S45°-58'-20"W

139.17'

Utility Pole N56°-19'-44"W

OFESSIONAL STATE

REF. MON.

S60°-50'-31"E

106.49'

Power Pole

N10°-41'-27"E

Surveyor's Michigan License No.

Date <u>April 29</u> 1996

t

t

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1871 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995