

SURVEY & REMONUMENTATION

APR 29 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

JUDITH D. ROEHM
Ontonagon County
LC 3/393 JEM Fee: 9.00
10/26/95
08:08
Page 1 of 1

For corners in

ONTONAGON
(County)

Located In:

Corner Code #

- | | | | | | |
|---------------------------------------|---|----|---|----|------|
| 1. Public Land Survey | T | 49 | R | 41 | C-11 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous | S | | T | R | |
| Property in Section | S | | T | R | |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Section Corner common to Sections 29, 30, 31, & 32, T49N R41W.

I, Earl W. Applekamp, in a field survey on July 22, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by S.W. Higgins, U.S. Deputy Surveyor, summer 1847. Set Post.

ORIGINAL BEARING TREES:

| | | | | |
|----------|-----|-------|----------|--------------|
| Cedar | 18" | N70°E | 24 links | (15.84 feet) |
| Y. Birch | 16" | S40°W | 38 links | (25.08 feet) |

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of the original corner or accessories were found. The area has been logged twice and burned over. The latitude of the corner position is on a line between opposite Section Corners East and West. The departure of the corner was arrived at by proportionate measurement between opposite corners East & West. This location agrees with GLO calls to three stream crossings East of this corner. The course of the streams are N30°-40°E. I monumented the Corner at this position as best representing the original corner location.

Research on file with the County Remonumentation Representative.

PEER GROUP APPROVED

Earl W. Applekamp
COUNTY REPRESENTATIVE
10-18-95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2½"x30" aluminum pipe with a ¾" cap stamped to read: COUNTY REMONUMENTATION, S29, S30, S31 & S32, T49N R41W, 1995, P.S. 17610. I established the following bearing trees and reference objects:

| | | | | | |
|----------------|-------|------------|--------------------|-------|------------|
| 4" Twin Maples | N74°W | 12.54 feet | - 9" Maple | S02°W | 18.92 feet |
| 5" Black Ash | N58°E | 22.23 feet | - Steel Sign Post, | North | 1.66 feet |



Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date July 22, 1995