

APR 29 1995

COMMISSION

JUDITH D. ROEHM
Ontonagon County
LC 3/395 JEM Fee: 9.00
Page 1 of 1

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in ONTONAGON Located In: Corner Code #
(County)

- | | | |
|------------------------------------|-------------------------|-------------|
| 1. Public Land Survey | T <u>49</u> R <u>41</u> | <u>E-12</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous | S _____ T _____ R _____ | _____ |
| Property in Section | S _____ T _____ R _____ | _____ |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

$\frac{1}{4}$ Corner common to Section 32 and 33, T49N R41W

I, Earl W. Applekamp, in a field survey on June 24, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by S.W. Higgins, U.S. Deputy Surveyor, Summer 1847. Set Post.

ORIGINAL BEARING TREES:

Balsam	8"	S50°W	16 Links	(10.56 feet)
Balsam	10"	N46°E	8 Links	(5.28 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original corner was found. Corner was re-established by single proportionate measurement between the Section Corner to the North & South. Corner position is in agreement with original field note calls and timber cutting to the West. I set a monument described in "C" below. This corner is one of 29 corners in 6 Sections remonumented under the County Remonumentation Program. Research is on file with the County Remonumentation Program Representative.

PEER GROUP APPROVED

Earl W. Applekamp
COUNTY REPRESENTATIVE
10-18-95

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a $2\frac{1}{2}$ "x30" aluminum pipe with a $3\frac{1}{4}$ " cap 2" below a dirt road surface. Cap is stamped to read: COUNTY REMONUMENTATION, $\frac{1}{4}$, S32, S33, T49N R41W, 1995, P.S. 17610. I established the following bearing trees and reference objects:

5" Aspen	S20°W	39.38 feet	3" Spruce	N45°E	37.40 feet
5" Aspen	S57°E	38.49 feet	Steel Sign Post, East		18.76 feet



Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date July 22, 1995