

SURVEY & REMONUMENTATION

APR 29 1996

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

JUDITH D. ROEHM 10/26/95
Ontonagon County 14:08
LC 3/369 MEL Fee: 9.00
Page 1 of 1

For corners in **COMMISSION**
ONTONAGON
(County)

Located In:

Corner Code #

- | | | | |
|------------------------------------|------|------|------|
| 1. Public Land Survey | T 49 | R 42 | C-11 |
| | T | R | |
| | T | R | |
| | T | R | |
| 2. Property Controlling in Section | S | T | R |
| | S | T | R |
| 3. Miscellaneous | S | T | R |
| Property in Section | S | T | R |

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Section Corner common to Section 29, 30, 31 & 32, T49N R42W.

I, Earl W. Applekamp, in a field survey on August 21, 19 95, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt, U.S. Deputy Surveyor in June, 1848. Set Ironwood Post.

Sugar 20" N40°E 8 Links (5.28 feet)
Sugar 8" S35°W 28 Links (18.48 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence was found. Corner position is on a gravel road running East with another road running North. A lesser maintained road continues to the west. Corner was re-established using the centerline of road running E & W and centerline of road running North. This position is in agreement with a stream call 3.55 Chains West and a stream call 8.05 Chains East. The position is in agreement with the original distances to the Sections Corners 1 mile East and 1 mile West. I set a monument described in "C" below. Research on file with County Remonumentation Program Representative.

PEER GROUP APPROVED

Earl W. Applekamp 10-18-95
COUNTY REPRESENTATIVE



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 2½"x30" aluminum pipe with a 3¼" cap stamped to read, T49N R42W, S. 29, S. 30, S. 31 S. 32, 1995, P.S. 17610. Monument is 4" below top of road surface. I established the following bearing trees and objects:

6" Maple N69°W 51.63 feet - 4" Maple S44°E 20.51 feet
5" Maple S62°W 29.59 feet - Steel Sign Post South 14.42 feet

Signed by Earl W. Applekamp
Surveyor's Michigan License No. 17610

Date June 05, 1995