

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 33 T 51N R 37W	5
	S 33 T 51N R 37W	PCC 3-5
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on PCC 3-5 04/07/2010 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 33) North 1/16 corner, Section 33. 1910 - Established by Engineer Gibbs and/or Fesing during a subdivision of Section 33, midway and on line between Center of Section 33 and North 1/4 corner, Section 33. No description of monument found. Bearing and distance south to Center of Section is S01 deg. 50'30"W, 1318.0'.

(PCC 3-5, Sec. 33) A point on the northerly E-W 1/16 line, Section 33, 1083.90' east of 1/16 corner #3 and 1625.87' west of 1/16 corner #5. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 33) Found a 1" ID iron pipe, approx 3.5' in length, in good condition, set firmly and apparently undisturbed, S01 deg. 47'02"W (true bearing) 1319.44' from the 1980 reestablished quarter corner F11 and N01 deg. 47'02"E 1319.19' from the reestablished Center of Section 33. The drawing of the 1910 survey indicates that the section was subdivided according to acceptable methods and I accept the pipe as a careful and faithful determination of the position of the corner. Placed an MDNR monument at the position of the pipe and set the pipe adjacent.

(PCC 3-5, Sec. 33) Established the position on a straight line between monumented 1/16 corner #3 1083.90' west and monumented 1/16 corner #5 1625.87' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
Set measuring nail with MDNR tag in the side of:
9" Sugar N14E 20.4' mrkd "1/16S BT"
5" Sugar S10E 16.3' do
11" Y.Birch S63W 24.7' do (old wire in tree)
13" Sugar N79W 13.4' do
Set sq'd cedar post adjacent. Bearings magnetic.

(PCC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" Sugar N66E 10.8' mrkd "POL BT"
6" Y.Birch S54E 18.1' do
9" Sugar S55W 7.1' do
9" Sugar N56W 14.6' do
Set sq'd cedar post adjacent. Bearings magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/07/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

