

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 29 T 51N R 37W	D10
	S 29 T 51N R 37W	12
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			32		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 12 04/13/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D10) Center of Section 29. 1939 - William A. Waara, Copper Range Co. found 1" iron pipe. P.A.L.
and W.A.W. [Peter A. Larsen and William A. Waara] marked 7" crotched s. map. N35W 13.8'. Y.tag on 7"
s. map. in clump of four, S45W 23'. 1980 - Recorded by K.L.Sackett, PS. Found iron pipe set on
section subdivision around 1900. M.C.Larsen has notes of survey. Found 1" iron pipe. 5" Sugar N51E
14.4', 9" Sugar S60W 11.4', 3" Sugar N80W 10.1'.

(12-Sec. 29) South 1/16 corner, Sec. 29. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D10) Found 1"ID iron pipe in good condition and at record bearing and distance from the 1980
witnesses. The Sugar NW is in good condition with double over-grown blazes. The remaining two BTs
are now dead. This corner was likely established around 1907 by W.B.Smith for Copper Range Co., or
by Fesing and Gibbs, ca. 1908-1910. Accepted the monument as a careful and faithful establishment of
the position of the corner.

(12-Sec. 29) Established the corner midway and on a straight line between Quarter corner 1293.43'
south and Center of Section 29 1293.43' north. The position for the corner falls on a north-facing
rock ledge and is not accessible. Established a Witness Corner on the N-S 1/4 line 24.31' south of
the corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D10) Found 1"ID iron pipe.
Set measuring nail with MDNR tag in the side of:
4" Sugar N77W 10.9' old blazes (1980 BT)
8" W.Spruce N58E 19.2' mrkd "C1/4 BT"
5" Hemlock S40W 1.3' do
5" W.Pine N46W 15.4' do
The 5" Hemlock was topped but should live.
Bearings are magnetic.

(12) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
for a Witness Corner 24.31' south of the corner
position and on the 1/4 line.
Set measuring nail with MDNR tag in the side of:
3" W.Pine N72E 17.5' mrkd "WC BT"
11" Hemlock S11W 1.8' do
8" Hemlock S52W 6.8' do
6" Cedar N07W 12.1' do
Set cedar post adjacent. Bearings magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/07/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

