

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon

(County)

Located In:

Corner Code #

1. Public Land Survey

T 51N R 37W

E12

2. Property Controlling
in Section

S

T

R

S

T

R

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

S

T

R

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 04/14/2010 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E12) Quarter corner common to Sections 32 and 33. 1846 - Established by S.W.Higgins Deputy Surveyor, midway and on the Section line between Section corners 40.00 chains north and south. Set post. Lynn 12 N80W 13 links, Lynn 10 S78E 26 links. The corner is shown on a mining company survey drawing, ca. 1907-1910 performed by W.B.Smith for Copper Range Co. and/or Engineers Fesing and Gibbs. The undated, unsigned survey drawing describes the subdivision of Sections 31, 32, and 33. Bearings and distances are given from E12 to the Section corners north and south, and to the Centers of Sections 32 and 33, west and east. No description of the monument is given. 1939 - William Waara for Copper Range Co. found 1.5" pipe 2.5' a.g. at fence cor. Put tag on 5" Elm N82E 22.5', marked 4" Elm N28W 14.3'. 1976 - Recorded by K.L.Sackett RLS. Found 1.5" ID iron pipe 28" above ground in fence line at corner of fences north-south-east. 7" Sugar N37W 12.0', 5" Sugar S55W 24.0'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E12) Found a 1.5" ID iron pipe in good condition, projecting approx. 2.5' above ground, in an old unmaintained N-S cedar post and 4-strand barbed wire fence, at record bearing and distance from the 1976 NBTs, both in good condition with old blazes. Measurements to adjacent Section corners confirms that this monument occupies the position described on the mining company survey drawing and I accept this monument as the best available evidence of the position of the original corner. The observed bearings and distances are: to E13 S1 deg. 04'44"E, 2740.94'; and to E11 N04deg. 12'50"E 2690.64' (True bearings). The old barbed wire fence is approx. 50% down on the ground between E12 and Highway M-38 and approx. 90% down on the ground from E12 to the north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E12) Found 1.5" ID Iron pipe.
Set measuring nail with MDNR tag in the side of:
6" Sugar S58W 24.3' overgrown blazes (1976 NBT)
7" Sugar N34W 12.3' scribing do
7" Ironwood S07W 9.0' mrkd "1/4S NBT"
10" Sugar N11W 19.3' do
Bearings are magnetic.



Signed by

Surveyor's Michigan License No.

33986

Date

09/07/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983