

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Ontonagon (County)	Located In:	Corner Code #
1. Public Land Survey	T 51N R 37W	D13
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 04/13/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D13) Standard Quarter corner on the south side of Section 32, on the 5th Correction line. 1845 -
Established by Austin Burt, who set post. 14" Sugar N68E 31 links, 7" Sugar N47W 24 links. 1907-
1910 Corner reestablished or remonumented by mining company surveyors W.B.Smith and/or Fesing and
Gibbs. Shown on undated and unsigned survey drawing at offices of Steven Hein PS, Laurium MI.
Bearings and distances to Section corners are given as N89 deg. 40'E 2639.50' to E13 and S89 deg.
56'W 2676.2' to C13. No description of monument. 1980 - K.L.Sackett RLS used a position midway and
on line between Section corners to partially subdivide Section 32. Position was not monumented.
1997 - J.C.Domitrovich PS 37273 reestablished and monumented a position equidistant between Section
corners and on the extension of a fence to west and distant centerline of Post Office Road to east.
Set 5/8"x24" iron pin with bronze Ontonagon Co. Remonumentation cap. Corner falls 15 feet west of
centerline of Post Office Road to North. 1997 position recorded in Liber 5 of LCR, Page 26.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D13) Found the 1997 monument and record accessories in good condition. The Easting of the 1997
position, being a reestablishment of the Easting of the 1980 position, conflicts with the dimensions
given on the old mining company survey. The mining company survey involves several sections and a
retracement of a large part of the survey this date reveals that the measurements were well made and
are reliable. I accepted the distances given on the mining company survey as the best available
evidence of the position of the original corner and I reestablish the Easting of the corner position
at the mining company distances to Section corners (prorated) N89 deg. 44'02"E 2639.47' to E13 and
S89 deg. 49'13"W 2676.17' to C13 (True bearings), and the Northing of the corner at the extension of
the old fence to the west, noted in the 1997 record. The position thus established falls at the
approximate intersection of the extended centerlines of Post Office Road north and east. With the
approval of Mr. Domitrovich, I removed the 1997 monument which I found S89 deg. 49'33"W (True brg.)
18.35' from the reestablished corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D13) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
0.1 ft. below ground. Fd. 1997 NBTs with measuring
nail and 1997 "Bearing Tree" sign:
11" Ash N43E 89.4' to found nail
11" Ash S89W 70.3' do
10" Ash N55W 36.8' do
S12E 11.1' to 6' tall steel sign post
"30141 Post Office Rd". Bearings are
magnetic.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/08/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division