

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Form fields for recording corner information including Ontonagon County, Location, Corner Code #, and survey details for Public Land Survey, Property Controlling in Section, and Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

Grid table for Register of Deeds Stamp & File Number with columns A-M and rows 1-13.

I, Stephan J. Szyszkoski, in a field survey on 08/12/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

- (1-Sec. 3) West 1/16 corner on the north line of Section 3, T51N-R37W. Not previously monumented.
(8-Sec. 9) Center-West 1/16 corner, Section 9. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- (1-Sec. 3) Established the position for the corner midway between Corners G1 1320.39' west and H1 1320.39' east and on the township line between standard corners G13 and H13 of T52N-R37W. Note that the cap of the monument placed at this position is improperly stamped, indicating that the the 1/16 corner is common with Section 34 T52N-R37W. It is not a common 1/16 corner.
(8-Sec. 9) Established the position for the corner midway and on a straight line between Quarter corner 1296.64' west and the Center of Section 9 1296.64' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

- (1) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. The cap is not properly stamped see note above. Set measuring nail with MDNR tag in the side of: 3" Oak N80°W 17.9' mrkd "1/16S BT" 10" Sugar N50°W 13.3' do 15" Sugar N34°W 21.8' do 3" Ironwood N04°E 13.8' do Set sq'd cedar post adjacent. E= 7848211.207 N= 231796.286
(8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 11" Maple N33°E 4.6' mrkd "1/16S BT" 10" Maple S49°W 5.7' do 8" Maple S64°W 5.7' do 9" Balsam N76°W 18.45' do Set sq'd cedar post adjacent. E= 7846583.242 N= 229373.422

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID RL0593: N= 221669.506 m. E= 7868965.488 m.

Signed by [Signature] Date 08/26/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

