

JUDITH D. ROEHN

1F

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

Ontonagon County

LC 5/309

Page of 1

DATE 07/10/2000

Time 12:13:34

RECORDING FEE:

9.00

For corners in

Ontonagon County Located in: Corner Code #

- 1. Public Land Survey T51N R39W L - 1
T R
T R
T R
- 2. Property Controlling in Section S T R
- 3. Miscellaneous Property in Sec. S T R

- 4. Lot No. , Recorded Plat
- 5. Private Claims

SURVEY & REMONUMENTATION

MAR 02 2001

SECTION

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Joseph C. Domitrovich, in a field survey on June 14, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(L - 1) North 1/4 Corner Section 1, T51N, R39W. * Note - This corner is not common with Section Corner to North.

This Corner was not set as part of the original survey. It was protracted midway between the township corner to the East and the NW Corner of Section 1 (Closing Corner) to the West.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I established corner midway between closing corner to the West and Township corner to the East and online between the Standard Corner to the West and Township Corner to the East. Corner falls 3.96' East of the South 1/4 Corner of Section 36, T52N, R39W and falls in low swampy area on the North side of power line clearing.


Research on file with County Remonumentation Representative.

EARL W. APPELKAUF
COUNTY REMONUMENTATION 6-21-00

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 2 1/2" x 30" aluminum pipe with a 3" diameter aluminum cap stamped to read: COUNTY REMONUMENTATION; T51N, R39W; 1/4; S. 1; C.C.; 2000; P.S. 37273. Ties:

7" Balsam	N 43°W	33.68'
8" Poplar	N 65°E	56.67'
Southerly Power Pole # 265	S 54°E	85.47'
Sign Rail	South	0.49' (to face)
S 1/4 Cor. Sec. 36, T52N R39W	S 89°52'50"W	3.96'
NW Cor. Sec. 1	S 89°52'48"W	2653.17'
NE Cor. Sec. 1 (Twp. Cor.)	N 89°52'50"E	2653.17'



NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted.

Signed by *J. C. Domitrovich*

Date 6/21/00

Surveyor's Michigan License No. 37273