LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	r corners in	Finity requirement of Act 14, whole F							
	Ontonagon (County)	Located In:	Corner Code ≠						
1.	Public Land Survey	T <u>510 r 400</u> T <u>510 r 400</u>							
		T R							
2.		s T R							
3	in Section Miscellaneous	S T R							

Register of Deeds Stamp & File Number

4.	Lot No	Recorded Plat	 	

5 Pris	vate Claims		

in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

^_	B	Ç	0	ŧ	_	u	<u> </u>	•	, P	·	N
	i	Γ	֡֟֟֟֓֓֓֓֓֓֓֓֟֟֓֓֓֓֟֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֓֟֓֓֓֓		Ì		iΠ				i –
							Ĺ				2
		Г.	i_				Ľ				
		L.	<u>[</u>	Ĺ		Ĭ				L.	Ĺ
	Ĺ		Ï	Ī	Ĺ						
_,		Ĺ.,				9				١.	_
		Ľ	Ĺ				Ĺ				
	Ĺ	L,		L,					_,	L,	
	Ĺ			Ľ			ί				
	Ļ	Ľ,		Ľ.				\Box	Ļ	L.	
		٦			Ĭ	Ğ		٦			
		Ī	181	7	19 17 1	19 17 18	3 - 5 - 4	5 4 3 3 4 5 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5 7 5 7	3 - 5 - 4 - 3	3 - 5 - 4 - 3 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2	3 - 5 - 4 - 3 - 2

A. Description of original monument and accessories and/or subsequent restoration:

(37) Quarter corner common to sections 14-23. ISIN-840N. Corner previously recorded by Rieth L. Sackett in 1976 as monumented by a I'I.D.x24' pipe with a 4' aluminum cap and the following NBTs: 5' maple MIZW 21.3' 1/45 MBT, 3' maple M22E 20.2' 1/45 MBT, 4' sugar \$72E 26.5' 1/45 NOT.

(K7) Section corner common to sections 13-14-23-24. Corner previously recorded by Kieth L. Sackett in 1976 as monumented by a 1"I.D.x24" from pipe with a 4" aluminum cap and the following MBTs: 10" ash \$58H 30.8' \$23 MBT, 7" ash M82W 46.9" \$14 MBT, Fence corner morth, 22'. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(37) Recovered the stumps of the three MBTs noted above, all in proper relation, two with lower blaze, scribing, and notch visible. Monument placed in 1976 was not recovered. Placed a new monument, a 1°1.0.x36° iron pipe capped with a 4° dia. cast aluminum MDMR tablet at record bearing and distance from the remains of the 1976 HBTs. Marked four new witness trees as described below. (R7) Monument placed in 1976 was not recovered. Placed a new monument, a 1'IDx24' iron pipe capped with a 4' dia. cast alueinum MDMR

tablet, at record bearing a distance from the two 1976 MBTs and the fence corner, noted above. The 10° ash MBT is dead. Both were found standing, with scribing visible. Marked three new witness trees as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J7) Set 1" pipe with 4" MDMR cap. Blazed and scribed the following new

(K7) Sot a 1 pipe with 4" HOHR cap. Marked the following new bearing trees:

bearing trees:

5" basswood M24E 24.6' "\$13 HBT" 3" R. Pine \$62E 30.2' "\$24 HBT"

8" eaple NISE 37.2' "1/45 NBT" 9" maple \$73M \$3.3' "1/45 MBT"

Property in Sec.

4" sugar \$22E 27.0" "1/45 MBT"

5" basswood \$588 37.3' "\$23 MDT"

3" basswood \$05W 18.2' "1/45 WBT"

Surveyor's Michigan License No. ____

ROYER BY MICHMEAN STATE ROARS OF LAND EURVEYDAS, JAM. 26, 1971 REVISED MAY 14, 1975 REVISED JAH., 1943