

JUDITH D. ROEHM

IP

LAND CORNER RECORDATION CERTIFICATE

Ontonagon County

Filing Requirement of Act 74, Mich. P.A. 1970

of 1
06/12/2000

LC 5/294
Time 16:36:37

RECORDING FEE:

9.00

For corners in

Ontonagon County	Located in:	Corner Code #
1. Public Land Survey	T52N R39W	M - 10
	T52N R38W	A - 10
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

SURVEY & REMONUMENTATION

MAR 02 2001

SECTION Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

I, Joseph C. Domitrovich, in a field survey on May 15, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A - 10/M - 10) 1/4 Corner Common to Section 25, T52N, R39W and Section 30, T52N, R38W.

1845 - William A. Burt Set a Fir post at the corner with ties:

20" Cedar	N 35°E	2 links
16" Hemlock	N 23°W	16 links

1935 - Ned and John Hawley, Timber cruisers, noted in their copy of the original notes that the original Hemlock was green and standing and that they replaced the fir post with a Hemlock stake.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found an intersection of old fences East and South which works well with remains of original Hemlock Bearing Tree to the Northwest, now a 28"+ rotten stump. I found no remains of the 20" cedar. This position works well with section corners to the North and South. I accepted this position as the 1/4 corner and placed a County Monument at it.


Research on file with County Remonumentation Representative.

DEED GROUP REPRESENTATIVE
Earl W. Koppelman
COUNTY REGISTERED 5-24-00

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner is a 2 1/2" x 30" Aluminum pipe with a 3" diameter Aluminum cap stamped to read: COUNTY REMONUMENTATION; T52N, R39W, R38W; 1/4; S. 25, S. 30; 2000; P.S. 37273. Ties:

6" Cedar	N 30°E	14.87'
Metal Fence Post	East	0.95'
6" Hemlock	S 33°W	9.33'
Metal Sign Rail	West	0.85'
5" Cedar	N 50°W	15.17'
8" Hard Maple	N 02°W	9.04'



NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted.

Signed by *Joseph C. Domitrovich*

Date 5/24/00

Surveyor's Michigan License No. 37273